UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION V CENTRAL DISTRICT OFFICE 536 SOUTH CLARK STREET CHICAGO, ILLINOIS 60605

Date: NOV 08 1990

Subject: TSP Compliance Inspection, Chemetco Foundry, Hartford, Illinois

(2-70-90)(AFH114:A6)

John J. Mc Guire, Environmental Engineer, From:

Central District Office(5SCDO)

To: Larry Kertcher, Chief

Air Compliance Branch (5ACB)

ATTN: Sharon Freeman (5ACB)

THRU:/ Willie H. Harris, Chief

Central District Office (5SCDO)

INTRODUCTION

In response to Mr. John T. Gaitskill's request dated July 27, 1990, I visited the subject facility on November 1, 1990, to conduct an inspection related to TSP Compliance. Specifically, the request was to: (1) observe and record visible emissions for one hour from the roof monitor; (2) observe and record visible emissions for one hour from each of the stacks; (3) verify furnace charging schedule; and (4) check the progress of the installation of air pollution control equipment. Mr. Mark C. Schlueter, Environmental Protection Engineer, of the Illinois Environmental Protection Agency (IEPA) met me at the facility after I completed the Visible Emissions observations. The facility was represented by Mrs. Michelle L. Resnack, Environmental Manager.

FACILITY DESCRIPTION

The Chemetco facility in Hartford, Illinois is a secondary copper smelter with a SIC code of 3341 (Secondary Smelting and Refining of Nonferrous Metals). The facility operates four furnaces. Emissions from each furnace are controlled by separate scrubbers. A small bag house was used to control fugitive emissions from with in the furnace building. A larger baghouse and new duct system was being installed to control fugitive emissions that are emitted from the roof monitor.

OFF-SITE OBSERVATION - PRIOR TO PLANT NOTIFICATION

Method 9 visible emissions observations were made of the roof monitor at the same location where past inspection were conducted. This location was off Old Alton Road on Oldenberg Road but east of gate. There was a no trespassing sign around this location. Chemetco is west of this location. At approximately 8:50am security personnel from Chemetco informed me that I was on the companies property. I informed them that I was with the USEPA, that I was taking Visible Emissions observations, and that I was outside of the company's gate. They stated that the company owned all land to the west of Old Alton Road. They called Mrs Resnack from there vehicle and she requested that I come to her office. At 8:57am I stop my observation of the roof monitor and went into the facility. I informed Mrs. Resnack of the inspection and then went back to the same location and continued to take visible emission observations.

Roof Monitor

Emissions were observed exiting the roof below the duct runs the length of the building. The emissions were read after the plume had risen above the duct and the sky was used as a background. The observations were taken formally for 35 minute (8:22 a.m. to 8:57 a.m.). Emissions ranged from 0% to 55%. The highest six minute average was 19.1% opacity. There were six reading greater than 30% but less then 60%. There were no readings greater than 60%.

While observing scrubber stacks emissions the roof monitor emissions ranged from 0% to 30%.

Scrubber Stacks

Method 9 visible emission readings were taken of scrubber stack #4 for 60 minutes (9:26 a.m. to 10:26 a.m.) after notifying the facility. Emissions were read two to three stack diameters from the stack after steam had dissipated. Emissions ranged from 0% to 100%. The highest six minute average was 32.9%. There were 36 readings greater than 30% but less than 60% and 5 readings greater than 60%.

While observing the roof monitor a black plume was observed from stack #4 at 8:29. This plum lasted for 2 minutes and ranged in opacity from 70% to 100%.

When scrubber stack #4 was emitting smoke the wind, which was from the south, prevented the observation of stacks # 1, 2 and 3. When emissions from stack #4 were 0, no emissions were seen from stacks 1, 2, and 3.

Other Observations

At approximately 10:30 a.m. I enter the facility and met with Michelle Resnack of Chemetco and Mark Schlueter of IEPA. The facility was operating normally. Mrs. Resnack stated that work was continuing on the installation of the baghouse that will control roof monitor emissions. A used baghouse was bought from Homestead steel. The unit is a Wheelabrator Jet II positive pressure baghouse. The installation of the

baghouse was complete. Work was continuing to finish the installation of roof sheeting, dividing walls, and fans. The system is expected to be operational by November 15, 1990. A stack test of the unit will be preformed within 60 days after start-up. This test is tentatively schedule for early January 1991.

All visible emissions readings, summary sheets, Chemetco Charging Schedule, and the State Notification sheet are attached. If you have any questions, please call me at (312) 353-2704.

Attachments

3:13:19 PM

THURSDAY

NOVEMBER 1, 1990

EVENT SURMA	₹ ₹	
101 HEAT T		
:40 479 RE	CHARGE	
6:40 270 BRZ		AP 2
:45 271 SM		ARGE
:20 479 RE	To Hamman	
:20 118 SME SLAG T	カタマの	
:30 479 RE	SPELT TRANS	
#33 118 SME SAMP B		
#34 118 SME SAMP B	L 60	
#35 119 REF CHARGE		
135 214 BRZ CHARGE		
:55 214 BR		
:00 271 SM		SLAG OFF
:00 214 BR		
:15 272 SM		CHARGE
#25 272 SM		8
:30 214 BR		
:45 479 SM		
:55 479 SM	LAY	
FOR DETAIL PF4 - FCE 4 - PF2 - F	FCE 2 PF1 - FCE 1	

m < m < N	T SUMMARY		
£ 1	1		1 1 1 1 1 1 1 1 1
6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6			
			SMELT TRANS
		TAP BLK CU	
MP RED. #2			
		DELAY	
	m		
	LAG OFF		
) 20			
	HARG		
	m m		
			LAG T
			SLAG TRANS
MP RED.#2			
	SLAG OFF		
AP 2ND MIL			
	REF CU SAMP		
ARGE			
	ဓ		
F4 - FCE 4	é	PF1 FCE	PF3 - FCE 3
	R G E R E ** R G E R E R E R E R E R E R E R E R E R	EVENT SUMMARY EVENT SUMMARY WETAL TRANS ARGE CHARGE REF CU SAMP ARGE SLAG OFF P 2ND MTL REF CU SAMP SLAG OFF P 2ND MTL REF CU SAMP ARGE FCE 4 PF2 FCE 2	EVENT SUPMARY 4 4 2 2 1 DELAY MP RED.#2 METAL TRANS SLAG OFF P 2ND MTL REF CU SAMP ARGE SLAG OFF P 2ND MTL REF CU SAMP ARGE SLAG OFF P 2ND MTL REF CU SAMP

SUMMARY OF VISIBLE EMISSION OBSERVATIONS - USEPA, REGION V

Source Identification

Facility: Chemeteo, Hartford, IL

Source: Roof Monitor

Regulation: Illinois 202(6)

Evaluator's Report

On November 1, , 1990, visible emission evaluation began at 8;22 and continued for 35 minutes.

SUMMARY OF READINGS


Time	0	Read	ings
Start-End C <u>S</u> T	Average	>30% to 60%	>60%
8;22 - 8:28	0	0	0
8;28 - 8;34	2.1	ð	0
8134-8140	12.1	3	0
8:40-8:46	19.6	3	0
8,46-8,52	6.0	0	0
8:52-8:57	6.0	0	0
	Start-End CST 8;22 — 8;38 8;28 — 8;34 8;34 — 8;40 8;40 — 9;46 8;46 — 8;52	Start-End Opacity CST Average 8;22 — 8;25 O 8;28 — 8;34 2,1 8;34 — 8;40 12,1 8;40 — 8;46 19,6 8;46 — 8;52 6,0	Start-End Opacity C5T Average >30% to 60% 8;22 - 8;28 O O 8;28 - 8;34 2,1 O 8;34 - 8;40 /2.1 3 8;40 - 8;40 /9.6 3 8;46 - 8;52 6.0 O

Readings ranged from O to 55 % opacity.
Meteorological Conditions: Cloud Cover
Ambient Temperature 60-62 °F.
Evaluation Conditions: Excellent Good Fair
Name and qualification of expert witness to attest to above:
Signature: Name: John McGuive Title: Environmental Engineer Office: CDO

Date of Last Certification: Dct. 4,1890

Initials of person who summarized data:

Date: 4 ///1/90			Fa	cilit	:y	<u> </u>	hemetco		 _			·· ·	•	
Observer: John McGuire						$-\mu$	artford	- 	/	··				
		Sec	0	15	30	1	Comments	\ C-	7		T	1		
Source: Secondary Copp Smelter Roof M	٠	Min	 	 	ļ	ļ	Comments	Min	١٠	1	1	 	Comr	
smelter koof M	onitar	0	0	2	0	0		30		15	10	0	Celi	te
- EVALD STONS			0		0	0		31	0		0	0		
Observation Point: Near g. OF Oldpabey Road (ate off	2	14	0	0	(C)		32	10	10	15	20		·•
6+ Clapabey Road (property line	3	0	0	0	0			10	0	0	10		n=10
		4	0	0	0	0	<u> </u>	34	10	0	0	0	Gard that I	5 BA
500.		5	0	0	0	0		35	<u> </u>					
Distance From: 400 Yards		6	0	0	0		white north	36	<u> </u>					
Direction From: S.E.		7	15	· .	-	0		37						
Source Height: 80ft		8	10	0	0	0		38						
		9	0	0	0	0		39						
Initial	Final	10	0	0	0	0		40						
Wind Direction ≤≤ω	554	11	0	0	0	0		41						
Wind Speed 10-15	10-15	12	\mathcal{O}		10	10	north.	42						
Sky Condition Mostly Suny	Mosty Sund		15		15	10		43						
Background Sky Ambient	5Ky				10	15		44						
Temperature of 600F	62°F	15	10	10	10	0		45						
Burnidity (high-low) 10w	low	16	0	0	0	0		46					 	
Color of Emissions White	white	17	30	35	45	50	White wid	47						
Reading Conditions Good	Good	18	55	35	35	20		48						
		19	20 1	15	25	30		49						
Plant Representatives: Non	œ_	20	30	20	15	20	`	50						
		21	20	15- 3	30	10		51			_			
State/Local Agency Representa	tives:	22	10 /	0	10/	5	Bleck-s	52		\dashv	\neg	_		 -
Nonz	\ A	23			15 1		Uhite N	53						 -
Dbservation.	·. .	24 /	0	01	0	0		54	7	\neg	1	_		
Began 8,22Am Ended 8	:56 Am	25	0 1	0/	01	0		55			-			
(CST)	<u> </u>	26 /	0 1	10/	0 (2		56	\neg		7	_	· · · · · · · · · · · · · · · · · · ·	
7	Stack #4	27	0	0	0	0		57	-		\neg	$\neg \neg$		
to 4+01 2 min. (70-1009)	7/40(11)	28	2/	3/	01	00	44,42	58	$\neg \neg$		7			
		29 (2/	0/	01	0		59	1	_	_	-		
Si42 Empésions from wa end of builday	u wi novi	Obser	ver's	Sig	nati	ıre	Dolla	M	1 < /	hu				1
inorg	•	Last (-44				··-		
***************************************		Obser												
	•					-:011								



SUMMARY OF VISIBLE EMISSION OBSERVATIONS - USEPA, REGION V

Source Identification

Facility: Chemetco, Hartford, IL

Source: Scrubber Stack #4

Regulation: Illinois 202(6)

Evaluator's Report

On November 1, 1990, visible emission evaluation began at 9;26 Am, and continued for 60 minutes.


SUMMARY OF READINGS

	lime		Read	ings
Set Number	Start-End C <u>s</u> T	Opacity Average	>30% to 60%	>60%
	9:26 - 9:32	0	0	0
7	19:32 - 9:38	10.8	0	<u> </u>
3	9:38 - 9:44	12.9	0	0
Ý	9:44 - 9:50	24.6	2	5
5	9,50-9,56	8.8	0	0
6	9:56 -10:02	3/,3	9	0
7	10:02 -10:08	30,8	7	0
8	10:08 - 10:14	32.9	13	0
9	10:14 - 10:20	21,5	3	.0
10	10:20-10:26	10,0	0	0

Desding would find a destall to 100 % appoints
Readings ranged from O to OO % opacity.
Meteorological Conditions: Cloud Cover <u>0%</u> .
Ambient Temperature 65-72 °F.
Evaluation Conditions: Excellent Good Fair
Name and qualification of expert witness to attest to above: Signature: Alm M. Aum Name: John Mc buire Title: Environmental Enfineer Office: CDO Date of Last Certification: Oct. 4, 1980

Initials of person who summarized data: Sfm

Date: ////90			Fa	cilit	у	(Themetc	J ·		··			
Observer: John McGuire		Hortford, IL											
		Sec	c o	1					cl	T -			
Source: Scrubber Stack	#4.	Min	0	15			Comments		10				Comment
		0	0	0	0	0	 	30	35	30	30	35	white
·			0	0	0	 _		31	3 E	25	30	25	
Observation Point: Near gats Oldenberg Road	e off	2	0	0	0	C)	32	25	35	30	35	
Oldenberg Road		3	0	0	0	0		33	35	30	30	35	
		4	0	0	0	0	 	34			-	35	
2		5	<u>(2</u>	0	0	0		35		+		35	
Distance From: 400 yd		7		0	0	0				+	 	30	
Direction From: SE			 ۲ –	0	0	\Box						35	
Source Height: 100f+	·	8	0				white	38	35	30	30	30	
		9	7——	10				39	30	30	30	30	
Initial	Final	10	20								_	30	
Wind Direction SSE	55E	11	1	20			· · · · · · · · · · · · · · · · · · ·	 			 	25	·
Wind Speed 10-15mph	10-15mph		20			_	· · · · · · · · · · · · · · · · · · ·	42	30	35	30	35	
Sky Condition Clear	Clou-	13		15	/ <u>~</u>	20			 	· · · ·	35	 	
Background SAy Ambient	Sky	14	-	25		25		44	30	35	35	35	
Temperature oF 65°F	7201		20			15					30		
Humidity (high-low) Low	1000		10		0	0			1		30		
Color of Emissions Whiteh	/	17		0	Q	0		47	30	35	35	40	
Reading Conditions Govl	Good		0		9	0		48	30	30	<i>3</i> 0	35	
		19		0	0	0		49	35	35	30	30	
Plant Representatives: 104 e	>	50		9	의	0		50	30	30	30	30	<u>.</u>
		21			I		Black				25	20	
State/Local Agency Representat	ives:		50					52	29	10	10	0	
Mone	1		20/		- 2\-	0		53	0	0		0	!
Observation.	14	24	~ 	0		9	•	54		0	 i-	<u> </u>	
Began 9:26 AM Ended 10	;26 AM	25 26	9		<u> </u>	0		55	0		0	2	
(EST)						0	white	56	0	0	0 1	7	
Remarks: Plume From Stock	14 obsural	27	0/				-5000						uh.te
OTHER Stack When Black Smi	one was that	28			<u> </u>	<u></u>		58					
Remarks: Plume from Stack of No Omissions From Stacks 1-	3 was act	29 /					——————————————————————————————————————	59				<u>5 </u>	·
most rhomiter Emissions	raugh From	Obser						<u>u 7</u>		Sh	سيا		71
0-30	,	Last	Cert	ific	ation	n D		4-9		-	, ,		
		Obser	'ver's	Af	filia	tio	n USE	FPA		•			



U.S. ENVIRONMENTAL PROTECTION AGENCY.

REGION V

 DIST	TRICT	OFFICE
 	* * * * * *	~ 1 1 1 -

STATE NOTIFICATION OF INSPECTION

Authority:	SECTION 114(d)(1)-CLEAN AIR ACT, AS AMENDED
_	CWA,TSCA,RCRA,SWDA
Source Name C	hemetco.
Address	
City Hart	Ford., IC
State I	
Person Notified (Tohn Justice 618-346-5770 Secretary to John Justice
O ganization	IEPA.
Date of Notification	10/26/90.
.	ection /1/// 40
	compliance monitoring, Enforcement Division request esc
VE	
-	
Scope VE	
Person Giving Notice	- John M. Sun
•	nental Engineer.
Organization C	

(Signature)

(organization)

Name of Source: chemetco

Observer: john mcquire

File Name: chmtco

Start Time: 0926 Stop Time: 1026 Date of Test: 11-01-1990

broke Shadi Milita Sweet salaha iliakka walita bisana sensus	men sepa new serie mae ess				GGREGATI		JUNES HARRY WHICH MAKES CHIEF MAKES	stud mass ower make once more	we have some while while who were
TOOT WHEN SEEN MICH AND SEELS COME AND AND	many result town from them will	ti 1880a shin shin sana dash de	. 101 many wore man min ha	mer kunna jagama kunna) ajamar maman) gamara maganj	speni come come prime sceni sceni sceni mario come pune meter sasce maser mune timo titolo succe	autho solvit vertir anne vitile imme	more and with ough must reco	, vadin surge werge, menje 19060. (plan	HATA labels from volen walds then
Sec>>	00	15	30	45	Sec>>	00	15	30	45
Min					Min				
1	VF9-	NAME	my	28/A-	31	35	4612	witer	35
e de la companya de l	and it	19495	mile		32	Jour	·····	75×	****
3	*iAu.	7570	640	*****	77	na maj	35	ntiben	35
44	A47=	ner	ada.	200	34	35	Maray		35
5	***	was	w/va	Ser.	35	nom ₂	Name of the last	****	35
6	uut	A PERSON NAMED IN COLUMN 1	nest.	note.	36	tan par	ma u	35	35
7	roms	PNGs	relan	****	37	Marri	lepro	ninaa	rani
8	byce;	_who	e ficiale.	annes	38		35	35	35
9	****	~~	****	woodi	39	35	-JAA	-	***
10	***	must,	√m)	alan	40	NAM of	relaye	windows.	
11	Time	-cost	444		41		ngwe;	TOM	· res
12	youn	, com	quick	716-7	42	35	35	ess.	P045
13	Name	~	nem.	adren	43	Make	35	navije	35
14	men	Mal	luci	****	44	2009	pm	35	Anna Anna
mg pane	majo	Wen	wnt		4. 6.	*	35	35	35
16	Lands	APP	way	ion.	46	35	35		35
17	14740	ens	Sec. Sec. Sec. Sec. Sec. Sec. Sec. Sec.	2mm)	47	35	Ineste	70	
18	Ame:	Auto		paca	48		35	35	40
19	-00	who	-	nergy)	49	18799	March Mark	men.	35
20	w	PRINT	*0***	1994	50	35	35	The special section is a second section of the second section of the second section of the section of t	~~
21	~~	was	-121	era	51		nun	****	il delete
: ££		100	100	100		-m-	ngm.	904	
23	50	75	85	45		AVV.00.	inter	1,006	marij
24		1 4m2	Day Carl	-s O	54	verge.	escore)		ian.
25	min		care.	нальну	S S	ou.ca	COLOR	No.	nuw.
26	Resign	MARKE	anger:	dom:	56	, m.er	die.	200	-070
27		vilens	****	.05u	57	NEW	-	w/m	***
28	~~		note:		58 58	#00m	laié.		-
29	FL/96	- Nation	Fun	10000	59		NAA.	304*	
30	ever.	-	Paris.		50 50	No.	1994 	- magnet	Steam

- The total time that the data is just GREATER than the given value of: 30 % Opacity is: 9.75 Minutes.

NOTE: violation is 1.75 minutes time between 30 460 mas 8 m

DATE PRINT: 01-01-1980

TIME PRINT: 00:03:29

^{*&}gt;> OPERATION WAS PERFORMED ON THE: original DATA. <<*

Tendall

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION V

DATE: JUL 1 1 1991

SUBJECT: Chemetco Briefing of Lead Pollution Prevention

Inspection/Meeting Kundell

FROM: Kendall Magnuson, Environmental Scientist

Enforcement Section

TO: Addressees

The inspection/meeting was conducted to discuss voluntary lead reductions as a pollution prevention measure. Chemetco is a secondary copper smelter using scrap brasses and bronzes as the charge and raw materials to produce an approximately 98.5% pure copper. The Environmental Manager is Michelle Reznack. We have set plans to arrive and meet with her and others from her department. There is the possibility that Jeff Benbeneck of IEPA, Region III in Collinsville, Illinois will attend with us. Discussions will center upon Chemetco's 4 top-blown rotary furnaces which are used in three modes of operation: smelting/slagging, refining, and melting. We will also touch upon any other points of lead emissions that become revealed to us when we learn more about the facility before and during the inspection/meeting. Ms. Reznack is currently preparing some information to be sent to us. The means by which Chemetco calculated its lead emissions is an issue to be clarified. We hope to observe the spectrum of the operation of the facility; from the receipt of raw materials to the storage of the final product.

June 30, 1988, Chemetco entered into a Consent Order with Illinois which stemmed from many violations of water, solid waste, and air regulations. The air violations were related to permitting of pollution control equipment and emission sources and opacity violations. The Consent Order stipulates limits of 20% opacity from scrubber stacks, roof monitors, any foundry openings, or any other emission points; and .022 gr/dscf for the concentration of particulate matter from any control device along with process weight rate dependent limitations in 35 IAC 212.321. Chemetco performed stack tests in February 1991. The results have not been received by IEPA, but indications are that Chemetco failed some parts.

<u>Addressees</u>

Diane Sipe Gustavo Felix standard bcc's: official file copy w/attachment(s)
originator's file copy w/attachment(s)
originating organization reading file w/attachment(s)

ARD:RDB:ES:MAGNUSON/nw:6-14-91 Diskette:G-Share Drive Saved: g:chemetco.kmm

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION V 536 SOUTH CLARK STREET

CHICAGO, ILLINOIS 60605

DATE: JUN 0 6 1990

SUBJECT: TSP Compliance Inspection, Chemetco Foundry, Hartford, Illinois

(4-2-90) (AFH114:E7)

FROM: Stephan Wynnychenko, Environmental Scientist $\sqrt{|\ell|}$.

Central District Office (5SCD0)

TO: Larry F. Kertcher, Chief

Air Compliance Branch (5ACB)

ATIN: Sharon Freeman (5ACB)

THRU: Willie H. Harris, Chief V

Central District Office (5SCD0)

iNTRODUCTION

In response to Mr. John T. Gaitskill's request dated April 9, 1990, I visited the facility on May 22, 1990, to conduct the first of three requested inspections relative to the TSP Compliance Investigation. Specifically, the request was to: (1) observe and record visible emissions for one hour from the roof monitor; (2) observe and record visible emissions for one hour from each scrubber stack; (3) verify charging schedule; and (4) check progress of air pollution control equipment installation. The Illinois Environmental Protection Agency was notified of the time and date of this inspection, but did not participate. The facility was represented by Mrs. Michelle L. Reznack, Environmental Manager, of Chemetco.

FACILITY DESCRIPTION

Chemetco Foundry, SIC code # 3341, is a secondary smelting and refining of nonferrous metals. The Chemetco foundry facility operates four furnaces. Currently, the fugitive emissions from these furnaces are control by a small baghouse located east of the plant. Uncontrolled emissions from the furnace operations escape to the ambient air through the roof monitor. Also, each furnace is equipped with a scrubber. These scrubbers are employed to control zinc oxides during the process operations, but not fugitive particulate emissions. Each scrubber has its own stack. The plant operates 24 hrs/day, 7 days/week, and 158 people are employed.

<u>OFF-SITE OBSERVATION - PRIOR TO PLANT NOTIFICATION</u>

ROOF MONITOR

Method 9 visible emission readings were taken from the roof monitor for 60 minutes (9:10 a.m. to 10:10 a.m.) prior to plant notification. Emissions ranged from 0% to 100% opacity. The highest six minute average was 78.54%

opacity. There were 98 readings greater than 30% (up to 60%) opacity. There were 49 readings greater than 60%.

SCRUBBER STACKS

Method 9 visible emission readings were taken from #2 scrubber stack for 42 minutes (10:25 a.m. to 11:07 a.m.) prior to plant notification. Emissions ranged from 0% to 35% opacity. The highest six minute average was 17.5%. There were 2 readings greater than 30%.

Scrubber stacks #1 and #3 were observed informally for 110 minutes (9:10 a.m. to 11:00 a.m.) and the opacity was zero percent. Visible emission observations on the scrubber stack #4 were not taken due to wind direction. The plumes emanating from the scrubber #4 stack were mixing with the roof monitor emissions before the steam dissipated.

The weather condition during this inspection was partly cloudy. Humidity was low, wind was from North (Northwest) at 5 to 8 miles/hour, and the temperature was 60 to 65 \deg F..

ON-SITE OBSERVATION

At approximately 1:30 a.m., I entered the facility and met with Mrs. Michelle L. Reznack, Environmental Manager. She explained that the plant was operating normally except for furnace #1. Furnace #1 was not operating and was down for bearing change. Also, she provided a computer printout which details the events that were occurring inside the plant at the time of this inspection (copy attached).

The facility is planning to install a new baghouse on the furnaces by July 1, 1990. At the time of this inspection the construction work for the new baghouse was completed and roof duct work was in progress to be installed. Mrs. Michelle Reznack explained that due to bad weather conditions the roof duct work is two weeks behind construction schedule time. Mrs. Reznack did not know the exact date when the entire construction on a new baghouse will be completed.

All visible emission readings, summary observations sheets, and State Notification sheet are attached.

If you have any questions regarding the inspection, please contact me at (312) 353-9153.

Attachments

	2 4 6		
Date: 5-22-90	Facility <u>CHEM</u>		
	Hart	ford, Ellivain	
Observer: S. WYNNYCHENKO			
Source: Secondary Copper.	Sec 0 15 30 45 Com	ments Sec O 15 30 45	Comment
SMELTER - Roof Mouitor	040404550 W	30 30 30 25 25	16-
- Eur'stions	150456070 W	31 31 40 40 40	g G
Observation Point: New gale all	270657070W	32 202020 40	96
Oldenberg Road property lin	3 61 60 60 va w	33 60 60 60 50	G
	4 45 40 40-50 W	34 50 60 60 70	(5-
	550504545 W	. 35 70 60 50 50	
Distance From: 400 yerr	6 416060806	36 6065 65 65	
Direction From: S E	7.80707080G	37 70 70 65 60	
Source Height: 80 Ft,	8 85 85 70 70 G	38 1010 3113	
	9 70 70 65 65 W	39 55 45 45 50	
Initial Final	10 100 100 100 100 G	40 60 60 65 50	
Wind Direction NW	11 100 100 20 20 G	41 10 60 60 60	
Wind Speed J-9 Whole	12 60 50 50 40 6	42 65 65 70 70	
Sky Condition Portly Cloudy Clear	13 40 40 45 45 6	43 70 70 70 70	
Background 1/4 / sty	14 40 35 35 36	44 75 8080 75	
Ambient Temperature °F 60 65	15 35 35 40 50 G		
Humidity (high-low) Cour Low	16 50 50 45 20 6	46 60 60 1010	
Color of Emissions White (area) white (bray)	17 30 30 30 35 B	47 50 50 1050	
Reading Conditions Socol Seed	18 25 25 20 20 W		w
7000	19 20 20 15 15 W	49 0202044	
Plant Representatives: 11 pulp	20 1/20 20 25 W	50 42 42 40 40	
W Mark	21 25 20 20 20 W	51 50 30 30 25	Con
State/Local Agency Representatives:	22 15 15 15 20 W		$\overline{\mathbf{w}}$
Nou e	23 15 10 10 15 W		w
	24 15 10 10 10 W	54 25 20 20 20 2	
Observation (1): (a)		55 20 20 2/ 20 8	
Began 9:10 a w Ended 10:10 a w;	26 (5 25 25 30 W		w
(,π)	27 30 30 25 25 W	57 0 0 1010 0	
Remarks:	28 30 30 30 25 W	1 1 1 1	W I
	29 25 25 25 25 W		w
5- groy to black		Or years	
5- black	Last Certification Date	4-5-90	
	1	es EPA	
	Observer's Affiliation U	·	

VISIBLE EMISSION EVALUATOR'S REPORT TO ENFORCEMENT

Source	Identification
200100	* CCH CITIC G CION

Facility: Chemetec, Hartford, Mi'uois

Source: Roof Monitor

Regulation: Illinois Rule 201 (6)

Evaluator's Report


On May 22	, 1990, visible	emission evaluation began at	9:10 a.m.
and continued for 60	minutes.	empaton evaluation began st	1,10 dille,

SUMMARY OF READINGS

	Time		. Rea	dings
Set Number	Start - End (C_T)	Opacity Average	30 to 60%	>60%
	9:10 - 9:16	.53,13	1-19	5
7	9:16 - 9:22	78.54	1. 3	21
3	19:11 - 9:128	40,21	20	
4	9:128 -9:34	18.33		
3	9:34 - 9:40	. 21.46		
6	9:40 -9:46	48.13	18	
7	9:46 - 9:152	57,92	1. 17	7
8	9:52 - 9:58	64,58	9	15
9	1.9:98 -10:04	31.67	12	
10	100,04-10110	. 11,67	-	

Readings ranged from to to to to to) % opacity.
Meteorological Conditions: Cloud Cover Par Ambient Temperat	
Evaluation Conditions: Excellent G	ood Fair
Name and qualification of expert witness to att Signature: 1. Trungelung Name: 1. WYNNYLHERIK) Title: Engineerial fur Office: CDD Date of Last Certification: 4-1	centro t

initials of person who summerized datas (1.4) /



AIM TOWARD SOURCE 9:150,00 810/15 see . OBSERVER (PLACE PEN AT CENTROID TO INDICATE SUN POSITION) Cherietco, Kortford, H 5-22-90 Roof Monitor observation parat Proposedy live

Source: S(VILLEWED) Sec O 15 30 45 Comments Main O O O O O O O O O	Date: 5-22-90	Fa	acili	у .	<u>C</u>	home.	tep				·	-
Source: Strubbley Shoth F Sec O 15 30 45 Comments Main O O O O O O O O O			5	-	11	artfor	d, d	lei'a	io	<u> </u>		
Source: Clouble State	Secretion 3, W/N N 7 CALINKO	N Sect	· 1		1		Neo	<u> </u>	7			
1 20 20 15 15 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	Source: Plantilon Strely #9	1 \ 1 ()	15	30	45	Comment	cı 🔪	0	15	30	45	Comment
1 20 20 16 16 16 20 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		0 20	20	20	25	G	30	0	0	0	0	
2		1 20	20	7	12		31	0	0	0	0	
Distance From: 400 Gived 5 20 X X X W 33 0 0 0 0 0 0	Observation Point: South cont oud	2 25	25	10	10	w	32	0	0	0	\mathcal{O}	
Distance From: \$\(\frac{1}{100}\) \(\frac{1}{100}\) \(\frac{1}{1	aft Oldenberg Raid new safe	100					33	0	0	0	0	
Distance From: \$\(\frac{1}{100}\) \(\frac{1}{100}\) \(\frac{1}{1	(property line)	4 ×	X	×	20	W.	34	0	0	0	O	
Source Height: 30 ft. 8 20 10 20 20 C 38 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0							35	0	0	0	0	
Source Height: 30 ft. 8 20 10 20 20 C 38 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	Distance From: 400 Gardy	6 🗡	×	2	30	W	36	0	0	0	0	
Sky Condition Pwylle Caudo 13 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	Direction From: SE	7.35	35	30	30	W	37	\Diamond	0	0	O	
Initial Final 10 20 25 20 6 40 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	Source Height: 130 ft.	8 20	20	20	20	G	38	0.	0	0	0	•
Wind Direction N	. 1	9 17	15	17	20	G	39	0	0	0	0	
Sky Condition Powler (burds 13 0 0 0 0 0 43 13 0 0 0 0 0 43 14 0 0 0 0 0 44 15 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	. <u>Inîtial Final</u>	10 20	25	20	20	G-	40	Θ	0	0	d	
13 0 0 0 0 43 14 0 0 0 0 0 44 15 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		11 2	Ó	0.	0	G	41	0	0	0	D	
14 0 0 0 0 44	Wind Speed # 5-8 mph	12 0	0	0	0		42					
Temperature of 15 0 0 0 0 0 45	Sky Condition Powlly Claude	13 0	0	0	0		43					,
Temperature of 64	Background Stry	14 0	0				44					
Humidity (high-low) Low 16 O O O O O O O O O O O O O O O O O O	Temperature °F 65	15 0	0	0	0		45					
17 0 0 0 0 47 18 0 x x x x 4		16 0	0	$\mathcal{O}($	0		46					
18		17 0	01	0 (47					
19		18 0	X	X- 3	\times		48					
Plant Representatives: Nove 20 0 ★ ★ 0 50 21 0 0 0 0 51 State/Local Agency Representatives: 22 0 ★ ★ 0 52 Nove 23 0 0 0 0 53 24 0 0 0 0 54 25 0 0 0 0 0 55 26 0 0 0 0 0 55 26 0 0 0 0 0 56 27 0 0 0 0 57 28 0 0 0 0 58 29 0 0 0 0 59		19 *	XI.	0] -	-	49					
21 0 0 0 0 51	Plant Representatives: Now			6	51		50					
Dbservation Began 10:20 aire, Ended 11:07 aire, 25 0 0 0 0 55 (it) Cemarks: Litertorence with the 700 0 0 58 W-white 23 0 0 0 0 0 53 24 0 0 0 0 0 54 25 0 0 0 0 0 55 26 0 0 0 0 0 56 27 0 0 0 0 0 57 28 0 0 0 0 0 58 29 0 0 0 0 0 59		21 0	00)		51					
Disservation Began 10:20 a.w., Ended 11:07 a.w., 26 10 0 0 0 0 55 (it) Lemarks: Letertage we with the 28 0 0 0 0 58 W-white 23 0 0 0 0 0 53 24 0 0 0 0 0 54 25 0 0 0 0 0 55 27 0 0 0 0 0 56 28 0 0 0 0 0 58 29 0 0 0 0 0 59	State/Local Agency Representatives:	22 0 3	X >	(5		52					
Began 10:21 a. w., Ended 11:07 a. w., 25 0 0 0 0 55 (IT) Lemarks: Leter for eure with the 28 0 0 0 0 58 W-white 29 0 0 0 0 59		23 0	0 0) ()		53					
Began 10:20 a.w., Ended 11:07 a.w., 25 0 0 0 0 55 (IT) Lemarks: Letertorque with the 27 0 0 0 0 57 Tool heurism plane 28 0 0 0 0 58 29 0 0 0 0 59	Dhearyation	24 () (0 () c			54			1		
27 0 0 0 0 57 28 0 0 0 0 58 28 0 0 0 0 58 29 0 0 0 0 59		25 0 0	9 C	0			55					
W-white 290000 - 59	Line (T)	26 (0) () ()		56					
W-white 290000 - 59	lemarks: de lead avenue antici de a	27 0 (- j			57		1	\top	1	
W-white 290000 - 59	Appli the Marian A Const.	28 0 0	0 0	10	1		58	\top	1	1	1	
	(w - whi be	29 0 6	2 0	$\int C$		-	59	1	1		\prod	
6- gray Observer's Signature Intillumithing		Observer's	Sign	atur	·e	5161	eur,	بليان	1			
Observer's Signature 1 to jump they Last Certification Date 4-5-90						e 4-1	5-90		/			


VISIBLE EMISSION EVALUATOR'S REPORT TO ENFORCEMENT
Source Identification
Facility: Chemeteo, Hertford, Millinois
Source: #2 serubber stack
Regulation: Illinois Rule 202 (b)
Evaluator's Report
On May 12, 190, visible emission evaluation began at and continued for 42 minutes.
SUMMARY OF READINGS
Time Read Start = End Onacity

	Time		Rea	dings
Set Number	Start - End (C_T)	Opacity Average	-30 to 60%	>60%
	10:25 = 10:31	. 13.54		<u> </u>
i i	10:31 - 10:37	17.5	2	
3	10:37 - 10:43	0,0	-	
<u> </u>	10:43 - 10:49	0.0		_
1	10:49 - 10:55	. D, O		
6	10:55 - 11:01	6, 0		
7	11:01 - 11:07	0,0		
	·	•		
		•		

10:25 axus

Readings ranged from
Meteorological Conditions: Cloud Cover <u>Partly Cloudy</u> Ambient Temperature 65°F.
Evaluation Conditions: Excellent Good V. Fair
Name and qualification of expert witness to attest to above:
Name: S. WY N'NY CHENCO
Name: S. WY N'NY CHENICO
Title: Euriron wental friendst
Office: CD D
Date of Last Certification: 4-5-90
·

initials of person who summarized data: $J_i\mathcal{Q}_i$,



AIM TOWARD SOUKCE € 10:20 a.di. 10-0 11:10 aiuv OBSERVER (PLACE PEN AT CENTROID TO INDICATE SUN POSITION) A 6 0 p 43 Chemeteo, Hartford, H 5-22-0,0 # 2 Serubber Hach observation por

VISIBLE EMISSIONS REPORT

				-	
Source Identifi	cation				
Facility:	Chemeter 1	Foundry, Ha	irtford, Alliha	ois	
Source :					
Regulation:	Minor Rule	202 (6)			
Evaluator's Rep	ort .	: • •			•
Juring the state	ed periods of ob	servation, the f	ollowing sources	appeared as	shown
Process or Source	Serubler Itack # 1	Scrubber Hack #3	Serubber Stach #4		
liate	5-22-90	5-22-90	V-22-90		
Obs. Time Start-End T	9:10 a.m.	9;10 aim. to 11:00 aim.	9:10 a.m., To 11:00 a.m.		-
Estimated Range of Opacity 0/0	0	0	ust bluferwind		
Operating?	No	yes.	400		
Control Device(s)	fisubles	se vu blee	pe public		
Emission Point	Stael	stoca	Stack		

liter mitoline lister took

monetor plung.

Hame and Qualification of expert witness to attest to above:

Remarks ·

Name :	S. WYNNY CHENKO	
Title :	Euripanmental Leve	ectiff.
Office :	CDO	

				,		F SUMMARY					
 3	5/22	HEAT	TYP 3	4	3	2	3	1	3	3	3 -3
 3	6:35	606	SME 3	•	3		3		3	Charge	3
3	6:39	606	SME 3		3		3		3	Slag Trans	3
3	6:40	530	REF 3	Slag off	3		3		3		3
3	6:45	523	BRZ 3	•	3	Blow Tap #1	3		3		3
3	6:4 5	530	REF 3	Ref Cu Samp	3		3		3		3
3	7:05	606	SME 3		3		3			Slag Trans	3
3	7:37	530		Tap Metal	3		3		3	T 11 M-L-1	<i>∃</i>
3	7:50	606	SME 3		3		3	ł	3	T.H. Metal	3
3	7:55	531		(Charge	3		3		3		3 3
3	7:56	531		7 Charge	3		3		3 3		उ उ
3	7:57	531		7 Charge	3		₹ 3		3		<u>उ</u>
3	7:58	531		7 Charge	3	Charan	3 3	1	3		3
3	9:10	523	BRZ 3		3 3	Charge Samp Red.#2			3		3
3	9:50	523	BRZ 3		3 3				3		3
	10:10	523 404	BRZ 3 SME 3		3	Semb Mensur	3	W		Slag Trans	3
3	10:15 10:20	606 606	SME 3		3		3	V		Tap Blk Cu	3
	10:25	523	BRZ 3			Tap 2nd Mtl			3	· ••••	3
 										منة كالسنة فينيث للسنة ينهين لسنوا ينهين وبدن ويونو ويزيز ويزيز ويزيو ويزين فينيا	_ #
	FOR D	ETAIL		PF4 - FCE 4		PF2 - FCE 2		PF1 - FCE 1		PF3 - FCE 3	
				EVI	EN'	T SUMMARY	<u>-</u>				
, " 3	5/22	HEAT			ΞN [*]	T SUMMARY 2	- <u>,</u> -	1	- <u>-</u> -		- , 3 -3
ਤ ਤੋਂ ਤੋਂ			· · · · · · · · · · · · · · · · · · ·	3 4	; - -3 -4·	2	+-·		 3 -+- 3		 3 -3
* 15 15 15 15 15	10:25	 523	BRZ 3	; 4 	 		+- 3 3	FUENACE #1	-+- उ उ		-3 3 3
ំ ។ ។ ។ ។	10:25 10:30	523 531	BRZ 3	3 4 	 	2	3 3 3	FURNACE # 1 DOWN FOR	-+- उ उ		-3 3 3 3 3
" ។ ។ ។ ។ ។	10:25 10:30 10:35	523 531 607	BRZ 3	4 G Metal Trans	3 -4 3 3	2	3 3 3	FURNACE # 1 DOWN FOR PM Bearing	-+- 3 3 3	Smelt Trans	-3 3 3 3 3 3 3
	10:25 10:30	523 531	BRZ 3 REF 3	 3 4 3 5 Metal Trans 3		2	3 3 3	FURNACE # 1 DOWN FOR PM Bearing	-+ 3 3 3 3 3	Smelt Trans	- ទី ទី ទី ទី ទី ទី
3 3	10:25 10:30 10:35 10:36	523 531 607 607	BRZ 3 REF 3 SME 3 SME 3	 3 4 3 5 Metal Trans 3		2 Tap 2nd Mtl	3 3 3 3	FURNACE # 1 DOWN FOR		Smelt Trans	-3333333 33333333
3 3 3	10:25 10:30 10:35 10:36 11:05	523 531 607 607 524	BRZ 3 REF 3 SME 3 SME 3	. 4 4 5 Metal Trans 6 Charge		2 Tap 2nd Mtl		FURNACE # 1 DOWN FOR PM Bearing (hange Delay		Smelt Trans	។ មានស្រាស់ មាន
3 3 3	10:25 10:30 10:35 10:36 11:05 11:30	523 531 607 607 524 531 693	BRZ 3 REF 3 SME 3 SME 3 SME 3 REF 3	 4 		2 Tap 2nd Mtl		FURNACE # 1 DOWN FOR PM Bearing (hange		Smelt Trans	ម្នាធានា មានក្នា
3 3 3	10:25 10:30 10:35 10:36 11:05 11:30	523 531 607 607 524 531	BRZ 3 REF 3 SME 3 SME 3 REF 3	4 Metal Trans Charge		2 Tap 2nd Mtl	+ 3 3 3 3 3 3 3 3 3	FURNACE # 1 DOWN FOR PM Bearing (hange Delay	+ 333333333	Smelt Trans	ម្នាធានា មានក្នា
	10:25 10:30 10:35 10:36 11:05 11:30 11:31 12:15	523 531 607 607 524 531 693 694	BRZ 3 REF 3 SME 3 SME 3 SME 3 SME 3 SME 3	4 Metal Trans Charge		2 Tap 2nd Mtl Charge		FURNACE # 1 DOWN FOR PM Bearing (hange Delay	+33333333333	Smelt Trans	ម្នាធានា មានក្នា
	10:25 10:30 10:35 10:36 11:05 11:30 11:31 12:15	523 531 607 607 524 531 693 694 524	BRZ 3 REF 3 SME 3 SME 3 SME 3 SME 3 SME 3	4 Metal Trans Charge Charge		2 Tap 2nd Mtl Charge Slag off	33333333333333333	FURNACE # 1 DOWN FOR PM Bearing (hange Delay Slag Trans	+ 333333333333	Smelt Trans	ម្នាធានា មានក្នា
3 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	10:25 10:30 10:35 10:36 11:05 11:30 11:31 12:15 12:15	523 531 607 607 524 531 693 694 524 531	BRZ 3 REF 3 SME 3 SME 3 SME 3 SME 3 SME 3 SME 3	4 Metal Trans Charge Charge		Z Tap 2nd Mtl Charge Slag off	333333333333333333333333333333333333333	FURNACE # 1 DOWN FOR PM Bearing (hange Delay	+ 3333333333333333	Smelt Trans	ម្នាធានា មានក្នា
S S S S S S S S S S S S S S S S S S S	10:25 10:30 10:35 10:36 11:05 11:30 11:31 12:15 12:15 12:15	523 531 607 607 524 531 693 694 524 531 524	BRZ 3 REF 3 SME 3 SME 3 SME 3 SME 3 SME 3 SME 3 SME 3	4 Metal Trans Charge Charge		Z Tap 2nd Mtl Charge Slag off	+ 3333333333333333333333333333333333333	FURNACE # 1 DOWN FOR PM Bearing (hange Delay Slag Trans	+333333333333333	Smelt Trans	ម្នាធានា មានក្នា
	10:25 10:30 10:35 10:36 11:05 11:30 11:31 12:15 12:15 12:15	523 531 607 607 524 531 693 694 524 531 524 694	BRZ 3 REF 3 SME 3	4 Metal Trans Charge Charge Charge Charge Charge Charge Charge Charge		Z Tap 2nd Mtl Charge Slag off	+ 3333333333333333333333333333333333333	FURNACE # 1 DOWN FOR PM Bearing (hange Delay Slag Trans	+333333333333333	Smelt Trans	ម្នាធានា មានក្នា
	10:25 10:30 10:35 10:36 11:05 11:30 11:31 12:15 12:15 12:15	523 531 607 607 524 531 693 694 524 531 524 694	BRZ CREE COME COME COME COME COME COME COME CO	4 Metal Trans Charge Charge Charge Charge Charge Charge		Z Tap 2nd Mtl Charge Slag off	+ 3333333333333333333333333333333333333	FURNACE # 1 DOWN FOR PM Bearing (hange Delay Slag Trans	+333333333333333	Smelt Trans	ម្នាធានា មានក្នា
333333333333333	10:25 10:30 10:35 10:36 11:05 11:30 11:31 12:15 12:15 12:15	523 531 607 607 524 531 693 694 524 531 524 694	BRZ CREE COME COME COME COME COME COME COME CO	4 Metal Trans Charge Charge Charge Charge Charge Charge		Z Tap 2nd Mtl Charge Slag off	+ 3333333333333333333333333333333333333	FURNACE # 1 DOWN FOR PM Bearing (hange Delay Slag Trans	+333333333333333	Smelt Trans	ម្នាធានា មានក្នា
তিতাতাতাতাতাতাতাতাতাত	10:25 10:30 10:35 10:36 11:05 11:30 11:31 12:15 12:15 12:15	523 531 607 607 524 531 693 694 524 531 524 694	BRZ REF SME SME SME SME SME SME SME SME SME SME	4 Metal Trans Charge Charge Charge Charge Charge Charge Charge Charge		Z Tap 2nd Mtl Charge Slag off	+ 3333333333333333333333333333333333333	FURNACE # 1 DOWN FOR PM Bearing (hange Delay Slag Trans	+ 3333333333333333	Smelt Trans	។ មានស្រាស់ មាន

PF4 - FCE 4

PF2 - FCE 2

FOR DETAIL

M. Heyret Anc.

PF1 - FCE 1

PF3 - FCE 3

U.S. ENVIRONMENTAL PROTECTION AGENCY.

REGION V

Central DISTRICT OFFICE

STATE NOTIFICATION OF INSPECTION

	OTTE NOTIFICATION	NOTECTION	•
Authority:	SECTION 114(d)(1)-(ILEAN AIR ACT, AS A	MENDED
		RCRASWD	
Source Name	CHEMETCO.		ሌ · -
	CHETCH		
Address	• '		
City HANTE	ORD, ILLINOUS		
State		-	
Person Notified	John	Questico 618-2	
 Title	-	Forther 010 >	16 NI 20
*	I EPA	-	
· ·		•	-
Date of Notification		5-1190	
: Planned Date of Ins	pection 5-12 (n 13)	-9 n	
ourpose of Inspection	on (compliance mentioring,		equest etc.)
	TSP Confloure	prisfigatives .	
	•	• •	-
cope	_		
erson Civing Notic	= SINGNNY CHENKS		
_	incurrental fectorist		· · · · · · · · · · · · · · · · · · ·
rganization USE		CDO	
		:	
		•	
	•	S. & Jeeny ale	
-	- 	(signature)	-
	_	CDO	-

(organization)

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION V

DAIE: JAN 11 1990

Chemetco Foundry, Hartford, Illinois SUBJECT:

(2-85-89) (AFH114:A2)

80

Basim Dihu, Environmental Engineer FROM:

Central District Office (5SCDO)

TO: Larry F. Kertcher, Chief

Air Compliance Branch (5ACB)

ATIN: Sharon Freeman (5ACB)

THRU: Willie H. Harris, Chief

Central District Office (5SCDO)

Acting on John Gaitskill's request of September 5, 1989, the subject facility was visited on October 19, 1989, to conduct the second of the three requested inspections related to the TSP Compliance. Specifically, the request was to: 1) observe and record visible emissions for one hour from the roof monitor; 2) observe and record visible emissions for one hour from each stack; and 3) verify production rates and time of charging and tapping at each furnace. The Illinois Environmental Protection Agency was notified of the date and time of this inspection, but did not participate.

Off Site Observations

On October 19, 1989, prior to entry into the facility visible emission observations were made at the following sources:

1 - Roof Monitor Emissions

Roof monitor emissions were taken by the writer for a period of one hour between 10:06 a.m. and 11:06 a.m. in accordance to Method 9, to assess compliance with Illinois Rule 202(b). The Illinois Rules specify that emission of smoke or other particulate matter from any such emission source may have an opacity greater than 30%, but less than 60% for a period or periods aggregating eight minutes in any 60 minute period. As shown by the attached observations and summary sheets, 66 readings exceeded 60% opacity.

2 - Scrubber Stacks

Visible emission observations on the four scrubber stacks were not taken due to weather conditions and wind direction. The plumes emanating from all four stacks were co-mingling with each other before the steam dissipated.

On Site Observations

At 12:00 p.m., I entered the facility and met with Jeff Zorger, Plant Manager.

Significant inspection findings are listed below:

- 1 The facility is planning to install a baghouse on the furnaces by July 1, 1990.
- 2 Attached to this inspection report is a computer printout copy provided by the company. This copy details the events that were occurring inside the company at the time of the inspection.
- 3 Also attached to this transmittal are copies of the visible emissions observation sheets, and summary sheet.

If you have any questions concerning this inspection report, please call me at 886-6242.

Attachments

n		Fa	.cilit	y .		CHEME	TC	0				····
Date: 10-19-89											· · · · · ·	
Observer: BASIM DHU	1					ARTF	ORD	7		上し.		
Source: SECONDARY COPPER	Sec Min	0	15	30	45	Comments	Sec	0	15	30	45	Comment
SMELTER- ROOF MONITOR	· · · · ·	50	50					10	10	15	15	
EMISSIONS	1	60	60	60	65		31	15		15	15	
Observation Point: OFF ROUTE	2	70	70	100	100	BLACK	32	15	15	10	10	
(3)	3	100	100	100	100	Middle menitor	33	10	10	 	70	BROWN.
	4	100	85	85	100		34	1-	-	65	}	Middle To NORTH Monitor
			100	!	+		35	 	25	+	10	Montre
Distance From: 300 YARD	6	75	70	70	70		36	10	5	5	5	
Direction From: 5W	7	65	75	80	85		37	5	5	5	5	
Source Height: 80 F7	8	85	85	75	75		38	5	5	5	5	
	9	70	70	65	65		39	10		10	10	
Initial Final	10	65	75	75	80		40	15	+	15	20	
Wind Direction NW	11	8 o	70	70	70		41	20		1	ZO	
Wind Speed 10-15 mpH	12	70	70	70	70		42	20	ZO	20	20	
Sky Condition OVER CAST	13	70	70	70	70		43	20	20	20	20	
Background SKY	14	65	65	 		GRAY ENLISS	44	20	20	20	15	
Ambient Temperature of 38°F 40°F			60	-		1-110076	45	15		5	5	
Humidity (high-low) Low	16	70	75	70	70			5		90	<u></u>	WHITE TO BROWN
Color of Emissions BLACK BROWN	17	60	55	50	45					45		- 13KJ W P
Reading Conditions FAIR	18	40	30	20	25		48	25	25	So	20	
reading Conditions 1 1112	19	25	20	20	15-		49	20	20	15	15	
Plant Representatives:	20		iS	ļ				-		10	├ — ┤	
NONE	21	Ιυ	5	5	5		51			10		
State/Local Agency Representatives:	22	5	5	5	5		52			25		
NONE	23	5	5	5	5		53	40	35	30	20	· <u> </u>
o	24	5	5	5	5					20		
Observation Began 10:06Am Ended 11:06AM	25	5	5	5	5		55			15		
	26	5	5	5	5		56			25		·
(T)	27	5	5	5	5		57	35	35	35	25	Bear
Remarks:	28	5	5	5	5		58					74.86. 0
	29	5	10	10	10		59	15	15	20	15	
	Obse	rver				Basi						
	Last	Cer	tific	atio	on C	Date /0-	10-	. 8	9			
	Obse						PA	\overline{c}	$\overline{\supset}$	0		
•			~ ' '		~ -10							

SUMMARY OF VISIBLE EMISSION OBSERVATIONS - USEPA, REGION V

Source Identification

Facility: CHEMETCO HARTFORD TLL

Source: SE CONDARY COPPER SMELTER - ROOF MONITOR EMISSIONS

Regulation: Illinois Rule 202 (b)

Evaluator's Report


On 10-19 , 1989, visible emission evaluation began at 10:06Am, and continued for 60 minutes.

SUMMARY OF READINGS

	Time		Read	lings
Set Number	Start-End	Opacity Average	>30% to 60%	>60%
•	10:06 Am - 10:12 Am	80,42	7	17
2	10:12 Am - 10:18 Am	73.54	0	24
3	10:18 Am - 10:24 Am	65,00.	7	17
4	10: 24Am - 10: 30 Am	13.13	1	0
5	10:30 Am _ 10:36 Am	5,63	0	0
6	10:36Am- 10:42 Am	23.\13	1	5
7	10: 42AM- 10:48Am	10.42	0	0
8	10:48 Am - 10:54 Am	28.96	3	3
9	10:54Am - 11:00 Am	20.21	2	.0
10	11:00 A 11:0 6Am	20.21	3	0

Readings ranged from 5 to 100 % opacity.
Meteorological Conditions: Cloud Cover OVER CAST.
Ambient Temperature 36-40 °F.
Evaluation Conditions: Excellent Good FairX
Name and qualification of expert witness to attest to above:
Signature: Bain Dolu
Name: BAZIM DIHU
Title: ENU ENG.
Office: こかり
Date of Last Certification: 10-10-89

Initials of person who summarized data: AD



U.S. ENVIRONMENTAL PROTECTION AGENCY.

REGION V

CENTRAL DISTRICT OFFICE!

STATE NOTIFICATION OF INSPECTION .

Authority: X SECTION 114(d)(1)-CLEAN AIR ACT, AS AMENDED
CWA,TSCA,RCRA,SWDA
Source Name CHEMET CO
Address
City HART FORD /
State FLC.
Person Notified John Justics
Title MANAGER OF AIR Pollution Control
Organization IEPA Collien sville Office
Date of Notification 10-11-89
Planned Date of Inspection 10-19-89
Purpose of Inspection (compliance monitoring, Enforcement Division request e
TSP Compliance
Scope TSP Compliance
Person Giving Notice BASIM 1HU
Title ENV. ENG.
Organization CENTRAL DISTRICT OFFICE
Barin Dilu
(signature)
(organization)

WCRKSTATION 196 - USER MLR - REZNACK, MICHELLE 219CRE

OCTCBER 3C, 1989

RONDAY

1:29:07 PM

#EAT TYP 4 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
5C E12 BRZ 116 588 SME 120 E12 BRZ 120 F12 BRZ 120 798 REF SMELT TRANS 120 798 REF METAL TRANS 130 798 REF METAL TRANS 131 798 REF 132 589 REF 140 636 SME 140 637 SME 15 E12 BRZ 16 636 SME 17. H., PETAL SAMP 16 637 SME 16 637 SME 17. H., PETAL SAMP 18 612 BRZ 19 637 SME 19 637 SME 10 637 SME 110 637 SME
15 588 SME 16 588 SME 17 589 REF 17 637 SME 18 512 BRZ 19 872 SME 10 637 SME 11 637 SME 12 638 SME 13 648 SME 14 648 SME 15 648 SME 16 648 SME 17 648 SME 18 648 SME
116 988 SME
2C 212 BRZ 2C 798 REF SPELT TRANS 3C 212 BRZ 3C 798 REF METAL TRANS 35 989 REF 36 5NE 37 5NE 36 636 SNE 37 636 SNE 37 5NE 36 637 SNE 37 637 SNE 38 612 BRZ 310 637 SNE 310 637 SNE 310 637 SNE 32 5NE 33 5NE 34 5NE 35 5NE 36 5NE 37 5NE 38 5NE 38 5NE 39 5NE 30 637 SNE 310 637 SNE 310 637 SNE 310 637 SNE 310 637 SNE
2C 798 REF SPELT TRANS 3C E12 BRZ 35 798 REF METAL TRANS 35 589 REF 36 636 SME 36 636 SME 37 689 REF 36 636 SME 37 588 REF 38 88 88 88 88 88 88 88 88 88 88 88 88 8
3C E12 BRZ 3C 798 REF METAL TRANS 35 989 REF 46 636 SME 36 636 SME 36 636 SME 37 SME 36 637 SME 37 SME 38 SAMF RED #1 38 SAMF RED #1 39 SAMF RED #1 30 637 SME 310 637 SME 32 798 REF 33 SAMF RED #1 34 SAMF RED #1 35 SAMF RED #1 36 SAMF RED #1 37 SAMF SAMF RED #1 36 SAMF RED #1 37 SAMF SAMF RED #1 36 SAMF RED #1 37 SAMF SAMF RED #1 36 SAMF RED #1 37 SAMF SAMF SAMF RED #1 36 SAMF SAMF SAMF SAMF SAMF SAMF SAMF SAMF
35 798 REF METAL TRARS 35 989 REF 36 636 SME 36 636 SME 37 636 SME 36 637 SME 37 637 SME 38 812 BRZ 39 812 BRZ 30 637 SME 310 637 SME 310 637 SME 310 637 SME 320 798 REF SLAG CFF
35 989 REF 4C 636 SME 145 636 SME 16 636 SME 16 637 SME 16 637 SME 16 637 SME 17 Hw PETAL SAMP 16 637 SME 17 Hw PETAL SAMP 16 637 SME 17 Hw PETAL SAMP 16 637 SME 16 637 SME 17 Hw PETAL SAMP 18 548 SAMP 18 54
4C 636 SME 45 636 SME 31C 636 SME 3C 636 SME 3C 636 SME 4C 812 BRZ 4C 812 BRZ 45 812 BRZ 45 812 BRZ 8LOW TAF #1 5LAG CFF
1C 589 REF 1C 589 REF 1C 536 SME 1C 536 SME 1C 537 SME 1C 537 SME 15 812 BRZ 15 812 BRZ 16 537 SME 16 537 SME 16 537 SME 16 537 SME 16 537 SME 17 841 18 841 18 841 18 848 18
10 589 REF 30 636 SNE 40 812 BRZ 10 637 SNE 45 812 BRZ 81.04 TAF #1 10 637 SNE 310 637 SNE 320 798 REF SLAG CFF
3C 636 SME 4C 812 BRZ 10 637 SME 45 812 BRZ BLOW TAF #1 T.H. 13C 798 REF SLAG CFF
CHANGE CHANGE CHANGE CHANGE CHANGE CHANGE SAME RED. # 1 SAME
11C 637 SME 15 812 BRZ 145 812 BRZ 145 812 BRZ 11C 637 SME 11C 637 SME 11C 637 SME
15 E12 BRZ 145 E12 BRZ 110 637 SME 130 798 REF SLAG CFF
:45 E12 BRZ :10 637 SME :3C 798 REF SLAG CFF
110 637 SME 13C 798 REF SLAG CFF
:3C 798 REF SLAG CFF
OR DETAIL PF4 - FCE 4 PF2 - FCE 2 PF1 - FCE 1 PF3

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION V

DATE: 10 OCT 1989

SUBJECT: Chemetco Foundry, Hartford, Illinois

(2-85-89) (AFH114:K7)

BD

FROM: Basim Dihu, Environmental Engineer

Central District Office (5SCDO)

TO: Larry Kertcher, Chief

Air Compliance Branch (5ACB)

ATTN: Sharon Freeman (5ACB)

THRU: Willie H. Harris, Chief

Central District Office (5SCDO)

Acting on John Gaitskill's request of September 5, 1989, the subject facility was visited on September 28, 1989, to conduct the first of the three requested inspections relative to the TSP Compliance Investigation. Specifically, the request was to: 1) observe visible emissions for one hour from the roof monitor; 2) observe visible emissions for one hour from each stack; and 3) verify production rates and time of charging and tapping at each furnace. The Illinois Environmental Protection Agency was notified of the date and time of this inspection, but did not participate.

Off Site Observations

On September 28, 1989, prior to entry into the facility visible emission observations were made at the following sources:

1 - Roof Monitor Emissions

Roof monitor emissions were observed by the writer for a period of one hour between 10:35 a.m. and 11:35 a.m. in accordance to Method 9, to assess compliance with Illinois Rule 202(b). The Illinois Rules specify that emission of smoke or other particulate matter from any such emission source may have an opacity greater than 30%, but less than 60% for a period or periods aggregating eight minutes in any 60 minute period. As shown by the attached observations and summary sheets, 87 readings exceeded 60% opacity.

2 - Scrubber Stacks

- a) Visible emission observations were observed from the North stack for a period of one hour between 11:41 a.m. and 12:41 p.m. in accordance with Method 9 to assess Compliance with Illinois Rule 202 (b). As shown by the attached observation and summary sheets, 82 readings exceeded 60% opacity.
- b) Visible emission observations were observed from the South stack for a period of one hour between 12:42 p.m. and 1:42 p.m. in accordance with Method 9 to assess Compliance with Illinois Rule 202 (b). As shown by the attached observation and summary sheets, 127 readings exceeded 60% opacity.
- c) Informal visible emission observations were made between 10:30 a.m. and 1:45 p.m. from the two middle stacks. The estimated range of opacities were 0-20%.

On Site Observations

At 2:00 p.m., I entered the facility and met with Jeff Zorger.

Significant inspection findings are listed below:

- 1 According to Mr. Jeff Zorger, the facility is under a Consent Decree with the Illinois Environmental Protection Agency.
- 2 The facility is planning to install a baghouse on the furnaces by July 1, 1990.
- 3 Attached to this inspection report is a computer printout copy provided by the company. This copy details the events that were occurring inside the company at the time of the inspection.
- 4 Attached to this inspection report is a copy of the Consent Decree.
- 5 Also attached to this transmittal are copies of the visible emissions observation sheets, summary sheets, and sun diagrams.

If you have any questions concerning this inspection report, please call me at 886-6242.

Attachments

U.S. ENVIRONMENTAL PROTECTION AGENCY.

REGION V

CENTRAL DISTRICT OFFICE !

STATE NOTIFICATION OF INSPECTION

Authority: X SECTION 114(d)(1)-CLEAN AIR ACT, AS AMENDED
CWA, TSCA, RCRA, SWDA
Source Name CHEMETCU
Address
City HART FORD
State ILU.
Person Notified DOHN JUSTICE
Title CHIEF AIR FOILHTION Section Collins Vill
Organization I EPA
Date of Notification 9-15-89
Planned Date of Inspection 9-28-89
Purpose of Inspection (compliance monitoring, Enforcement Division request etc
TSP Compl
Scope TSP Comp.
Person Giving Notice BASIM DIHU
Title ENV. ENG.
Organization CENTRAL DISTRICT OFFICE
Basin Dilu
(signature)
CD0
(organization)

SUMMARY OF VISIBLE EMISSION OBSERVATIONS - USEPA, REGION V

Source Identification

Facility: CHEMET CO HARTFORD, ILL

Source: SECONDARY COPPER SMELTER - THE SOUTH STACK

Regulation: Illinois Rule 202(b)

Evaluator's Report

On 9-28 , 1989, visible emission evaluation began at $12:42 P_{m}$ and continued for 60 minutes.

SUMMARY OF READINGS

	Time	0	Read	lings
Set Number	Start-End CT	Opacity Average	>30% to 60%	>60%
1	12:42 Pm - 12:48 pm	85.83	0	24
2_	12:48 pm - 12:54 pm	71.67	0	24
3	12:54Pm - 1:00 Pm	65.83	7	7
U	1:03 Pm - 1:06 Pm	69.79	O	24
5	1:06 Pm - 1:12 Pm	58.75	7	13
6	1:12 Pm - 1:18 Pm	27.50	9	0
7	1:+8 Pm - 1:24 pm	26.67	7	0
8	1:24 pm - 1:30 pm	37.92	i	. 7
9	1:30 pm - 1:36 pm	68.21	2	12
10	1:36 Am - 1: 42 pm	63.75	2	6

Readings ranged from 15° to 90° % opacity.
Meteorological Conditions: Cloud Cover $CLEAR$.
Ambient Temperature°F.
Evaluation Conditions: Excellent Good Fair
Name and qualification of expert witness to attest to above:
Signature: Basin Delin
Name: BASIM DIHY
Title: ENU. ENG
Office: CDO
Date of Last Certification: 4-10-87

Initials of person who summarized data:

		Fac	cility	J	· C	HEME	= 7	- <	_ (5		•
Date: 9-28-89			,	' -								
Observer: BASIM DIHU				-	+1	ART FE	SRI	ر د	D	(_,		
	Sec	0	15	30	45	Comments	Sec	0	15	30	45	Comments
Source: 35 COMPNAL CALLER	Min	90	90				Min 30	20	20	20	25	
SMELTER- THE SOUTH			90				31	1	25			
STACK	2		85				32	15	15	ļ	15	
Observation Point: 6ff 0F			85				33	L		L		-
OLDEN BERG RD	<u> </u>	90					34	<u> </u>	40		L	-
	<u> </u>		80				35		45		<u> </u>	
	L		800				36		40			
Distance From: 350 YARI)							37	ļ	35			
Direction From: 5E	8		70	70			38	 	20		20	
Source Height: 83'		70	70	70			39	 	20	ļ		
	9	70			70				25			:
Initial Final	10			65			40	ļ	20		\	
Wind Direction	11	70			├		41		20	<u> </u>		
Wind Speed 2-7MPH	12		70	70			42	!	20			
Sky Condition Some clouds	13	_	76			/	43	<u></u>	20	ļ <u></u>		Heavy
Background BLUE SKY Ambient			65				44	└	<u> </u>		<u> </u>	Heavy BHISSION FRO The roof
Temperature oF 70			60				45	 	25			monitur
Humidity (high-low) Madium			65				46	-	80			
Color of Emissions WHITE	17		70				47		70			
Reading Conditions GOON	18		70				48	70	70	70		
	19		70				49	X	X	X	*	`
Plant Representatives:	20		65				50	X	X	X	X	
NONE	21		65				51	X	X	70	70	
State/Local Agency Representatives:	22		70				52	70	70	70	70	
NONE	23	75		75			53	!	60		<u> </u>	
Observation	24	ļ	70			1 - 1	⁷⁶ 54	60	65	65	60	. •
Began 12: 42 pm Ended 1:42 pm	25		75			the south	55	65	65	65	65	
(* T)	26						56	4	*	X	X	
Remarks (X) Fm, SSidn S	27	60	60	60	60		57	*	*	*	*	
Remarks: (X) Emissions From The roof manison	28	60	60	60	65		58	X	X	X	X	
Cover The Stack Blacked	29	25	25	15	25	L	59		×	×	Х	
COURT THE Stack Blacked	Obse	rve	r's S	igna	ture	. Bas						
						Date 4-	10 -	8	9			
	Obse	rve	's A	ffili	atio	on US	EP_{I}	9. /	10	7	0_	

AIM TOWARD. SOURCE HARTFORD, III 9-28-89 Bann Dilm The South Stack OBSERVER (PLACE PEN AT

CENTROID TO INDICATE

SUN POSITION)

0 0 0 CLDENBERG RD. M ROUTE

> CHEMETCO HARTFORD, ILL

SUMMARY OF VISIBLE EMISSION OBSERVATIONS - USEPA, REGION V

Source Identification

Facility: CHEMETCO HART FORD, ILC

Source: SECONDARY COPPER SMELTER - ROOF MONITOR EMISSIONS

Regulation: Illinois Rule Zo2 (b)

Evaluator's Report

On 9-28 , 1989, visible emission evaluation began at $10.354 \, \text{m}$; and continued for 60 minutes.

SUMMARY OF READINGS

	Time	0 ''	Read	dings
\ Set Number	Start-End	Opacity Average	>30% to 60%	>50%
i	10:35 Am - 10: 41 Am	78.5	0	24
2.	10:41Am - 10:47Am	61.04	3 4	13
3	10:47Am - 10:53Am	45,00.	24	
ч	10:53 Am - 10:59Am	42.08	20	0
5	10:59 Am - 11:05 Am	3,96	0	0
6	11:05 Am - 11:11 Am	25·4Z	1	4
7	11:11Am - 11:17Am	19. 79	0	0
8	11:17A 11:23AM	41.25	0	7
9	11:23Am - 11:29 Am	95.21	0	24
10	11:29Am - 11:357m	63,75	9	15

Readings ranged from O to 100 % opacity.	
Meteorological Conditions: Cloud Cover CLEAR.	,
Ambient Temperature 65°F.	
Evaluation Conditions: Excellent Good Fair	
Name and qualification of expert witness to attest to above: Signature: Rasim Diffu Name: BASIM DIHU Title: ENU ENG. Office: CDO Date of Last Certification: 4-10-89	


Initials of person who summarized data:

		Fac	~ili+v	ص	\subset	HEME	TC	20				•
Date: 9-28-89		1 0.0	-1116	,	- "						<u> </u>	
Observer: BASIM DIHU		,		_	†	HART FO	OLD	/_	<i>F</i> (
	Sec	0	15	30	45	Comments	Sec	0	15	30	45	Comment
source: 520 cr 5, 5617.	Min\ O		80			Emissions	Min 30	5	5	5	5	WHITE
SMELTER- ROOF			80 80				31	5	5	5	5	
MONITOR EMISSIONS			90			WHITE TO	3.2	5	5	5	5	
Observation Point: OFF & OLDENBURG	3		90		1	1 - 1 - 1 - 2 - 4 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	33	5	7	5	5	+
ROAD	4		65				34	10			90	South t medile mon
			65	ļ <u> </u>]	35			80		middle.
2 - 440 -	6		65			 	36			15		mon'dor
Distance From: 350 YALD		<u> </u>	65		<u> </u>		37			25		500 TH monitor white robi
Direction From: SE	<u>'.</u> 8	ļ	60			 	38	25	ļ	20		<u> интекова</u> 1
Source Height: 80 F Y	9	<u> </u>	65	1	<u> </u>		39	15		25		
·		<u> </u>	60	l	<u> </u>		40			20		
Initial Final			50		 	 	41	15		15		
Wind Direction		 	50	 	 	<u> </u>	42	10	 		15	
Wind Speed 2-7MPH >			45				43	15		15		
01			50	1			44	15	15	15	15	1
Ambient	15	 	40		+		45		<u> </u>	25		,
Temperature of 65			40	1		J	 	 	 	100		NORTH
Humidity (high-low) Medium	17		45	I		I	47	—	 	100		WHITE TOYET
Color of Emissions WHITE			40		ļ	 	 		 	100	-	l
Reading Conditions (900)		1	45			l .						WHITE)
		1	45		·	 		 		100		····
Plant Representatives:	21		45		+	- 	 		<u> </u>	100	 	
NONE	22		50	1		. L		 		90		<u> </u>
State/Local Agency Representatives:	23	1	25			, ,				85	1	
7000	24	12	5	5	7	₩			ļ	80 80		ļ <i>j</i>
Observation	25	10	6	0	6	•		70		70		
Began 10:35AM - Ended 11:35A M	26	6	0	5	5	WHITE	56			65		
(⁻ T)	27	5	5	5	5	NORTH Side	 		ļ <u>.</u>	65		- Y -
Remarks:	28	5	5	5	5		 	17-	 	50	-	
	29	5	5	5	5	11	1	<u>t</u>		50		
	L	1-/	ر <u>۔ ا</u> امام	1	1	e Bas			lus	1-0		<u> </u>
			r's S				.10 -					<u> </u>
						() < 9) 7		
	Obs	erve	r's /	۱tfi.	<u>liat</u> i	on C	,	,	- (

CHEMETCO AIM TOWARD .; SOURCE HART FORD, IL 9-28-89 Basum J JECONDARY COPPER Smalter-Root monitor Emissiund OBSERVER (PLACE PEN AT

OBSERVER (PLACE PEN AT CENTROID TO INDICATE SUN POSITION)

N



CHEMETCO HARTFORD, ILL

Source Identification

Facility: CHEMETCO HARTFORD, FL

Source: SECONDARY COPPER SMELTER - THE NORTH STACK

Regulation: Illinois RULE 202 (b)

Evaluator's Report

On 9-28, 1989, visible emission evaluation began at 11:41Am, and continued for 60 minutes.

SUMMARY OF READINGS


<u> </u>	lime		Read	dings
Set Number	Start-End C_T	Opacity Average	>30% to 60%	>60%
1	11:41Am-11:47Am	49,29	21	0
2_	11:47 Am - 11:53Am	49.58	Ø	4
3	11:53 Am - 11:59 Am	80,00	0	2.
Ч	11:59 Am - 12:05 pm	30.00	0	24
5	12:05 pm. 12:11 pm	77.08	0	24
6	12:4 Am - 12:17AM	30.42	O	8
7	12:17 Pm - 12:23 Pm	11.67	0	20
8	12:23 Pm - 12:29 Pm	14.88	0	Q
9	12:29pm - 12:35pm	8 96	٥	. 0
10	12:35 PM - 12:41PM	3.86	0	0

Initials of person who summarized data:

- 101 28 1050		Fac	cilit	У_	· <u>C</u>	HEME	<u> </u>	- <	<u>,</u> (>_		
1ate: 5EPt. 28, 1989 1)bserver: BASIM DIHU				-	H,	ARTFOR	5 P^	7				
ource: SECUNDARY COPPER	Sec Min	0	15	30	45	Comments	Sec Min	0	15	30	45	Comments
SMELTER- THE NORTH	0	45	45	50	45		30	75	80	75	75	
STA CK		55	45	45	45		31	15	10	5	5	
Observation Point: OFA OF	2	45	45	<i>5</i> 0	55		32	5	-5	5	5	`
OLDENBERG RD	3	<i>55</i>	50	55	55		33	5	5	Į.	5	
	4	<i>5</i> 0	50	30	50		34	5	5	5	10	
	5	50	×	X	*	-	35	70	80	85	90	
Distance From: 350 YAKI)	6	X	*	*	*		36	90	90	80	85	
Distance From: 350 YARD Direction From: 5E	7	*	*	X	X		37	90	90	90	90	
ource Height: 85 F 7	8		×		1		38	80	80	80	80	
ource rieight.	9		25					1	1	80	1	
Initial Final	10	25	25	25	25				_	85		
Vind Direction S	11	100	100	/00	100	<u> </u>	41		<u> </u>	10	 	
Vind Speed 2-7 MPH	12	-	*	ļ	*		42	5		5	5	
iky Condition SCATTERD	13	· ×		*	<u>→</u>			5	0	0	5	
Background SKY (BLUE)	14	1	-		*					30		
3 1 1	15	 	×	1 .			45			25	 	
Temperature of 70 70	16	X	 - , -		—		46	<u> </u>	<u> </u>	30	<u></u>	
dumidity (high-low)	17		*	1		<u> </u>	47	•		15	L	
Color of Emissions WHITE			80					!	İ	15	· -	
Reading Conditions Goad							48			I		
		<u> </u>	80	-			49		1	 	5	
Plant Representatives:	<u> </u>		15				50	5	 -	0	0	
		1	80		<u> </u>		51	10			5	
State/Local Agency Representatives:		1	85				52		10	10	10	HEADEV PIACE
			85		 		53			10	ــــــــــــــــــــــــــــــــــــــ	HEAVEY BIACK EMISSION
Observation			70						*		×	Trad my Xy
Began 11:41 Am - Ended 12:41 pm			70							10	10	
(° T)		ļ	80	<u> </u>	!		56	5	5	5	5	
Remarks: (*) EMISSIONS FROM	. 27	75	75	80	80		57	5	5	5	5	
THE ROOF MONITOR BLOCKED	28	85	85	80	80		58	5	0	0	0	
COVER THE STACK - BLOCKED	29	80	80	80	80		L	5			9	
MY VIEW	Obse	erve	r's S	igna	ature	· Ba	in	T	لمأند	~		
	Last	: Ce	rtifi	cati	on l	Date 4	10 -	80	1			
	Obse	erve	r's A	۱ffil	iatio	on USE	PA	/ <		0		,·

AIM TOWERD HARTFORD, IL 9-28-89 Basin Dilin SECONDARY COPPER Smelfer THE NORTH STACK 11:40 Am 12:40 pm OBSERVER (PLACE PEN AT
CENTROID TO INDICATE SUN POSITION)

-



CHEMETCO HARTFORD, ILL

USER PLR - REZNACK, MICHELLE 219 CRE

) ;	1985
11: 420	SEPTENBER 297
שיי האים אין יי עיני	FRIDAY
SCRESIALICS -	1:42:38 PM

			EVEN	1 SUMMARY		\$ \$ \$ \$ \$ \$ \$ \$ \$
7	1 4		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		, , , ,	} 9 8 9
Mul	1 205	1 267			CHARGE	i 5 4
, K	െ	35			1	SLAC CFF
	\circ	3-		:	回り はくよつ	
 	O.			SLOW TAF #1	4 1	
0:4	\circ					
0:4	3	111	SLAG CFF		2 6 9 1	
4:1	()	> `			ルスモエー コベコン	
4:1	¬`	CY		ANGE I		
7:1	σ	Œ		٠ <u>٠</u>		
7 11 7	<i>></i> ^	LLI	TAP METAL		10 to	
5:0	ر, ۲	2			SLAC - XXXV	
5:0	, r	-11	HARG			
5:0	1	LU:				
2:5	ויי	i Li	HARG			o c
ν. 	1.0	≥_			5) () ()
``	الرا	2_		•	こう とばい エメー	
5:1	ഗ			BLOK TAF #1		
5	1. 1	од П	MELT TRAN			1888 98 98 98 98 98 98 98 98 98 98 98 98
	1 F	ą.	7 H H H H H T T T T T T T T T T T T T T	2 - FCE 2	O.	PF3 - FCE 3
ر ک	ا - ا					

}

SEPTEMBER 29, 1989

				* SE A R X	1	
16	1 #	L				
1 *	i m. i	1 SKE			CHARGE	
* * 5	45 52	S 30				7 6 4
* 8	δ. RJ	S 6 E			4	* RAFICE
.	C V	1 S.N			SPAFIE SIBE	(4
* 4	C)	€ S.×				ac. ⊲ ⊲C. ≺
	1.71 17.1	SS				.⊅ ≈ ≪ E
√ 3	C S				CFARGE	
N.F.	, C	₩ ₩		CHARGE		
C)	λ. 	\$ \$ \$ \$	SLAG CFF			
N	υ'n.	1 ₹20			SAMPLE SLAG	
⊘1	κ) ~	30 30 30 30	CHARGE			
N.	Ċ.	(E)		SLAC IRANS	,	
⊘	λ. Oz	<u>~</u>			SLAC CFF	
Ň	ξ.)	& ∞ m	REF CL SAND			
.0	ر د	1 SW			TAP BLK CL	
'n	ان د	, , , ,		SAME RED. #1		; ; ;
;√) 4 b	c) RJ	S. S				METAL TRANS
4 14.) 8.8	λ À	S)			CT AS GE	!
) (+ 4 1 1 1 1 1 1 1 1 1	F		_ <	PF1 FCE	س ب ب
	→ ←	_] -	j -	•	

REZNACK, MICHGLLE 21908E ğ ė CAN NOT LE LONK DE

不 一个 中中 二

· · · · · · · · · · · · · · · · · · ·	黄 食 1/2 寒 寒	第 2 m	· · · · · · · · · · · · · · · · · · ·
		AREA BYTHR KEY TO PAGE. FF 16 TO RAIL	α.
			KINDEL BY NCY
			CONSENT
		KEN REDUCED FIRING BATES TO MINIMIZE SMOKE	
		BENEFIT FRE FAU POUND CIT	CORRECTIVE ACTIONS
		INC CURRENCE	CALUM LINEOARD BEAAR
			ANDERS OF THE STORY
		SLANTITY OF MPIRSIONS PINITERIA	
		Since	X
7	2		
		MAN WAY IN MOTIONAL AND MAN WAY	CATALY INTERIOR
		T CONDITION REFOR	_ ∞ ⊃
		SACTAGE	
	者 放 放 放 放 放 放 放 放 放 放 放 放 放	英国法 提供 不不 有	超級 有效 乳液 渐放 有状 有衣 在衣 有故 我外 黑衣 班
) * 0 * 0 * 0 *	1	いさいり こうえのしのい きいとこう へのしのいきいとこう へのしのかきいとこう へのしのいき き	コンスのこのハチコン にったのこのハナの

ロボンハーソ	
1910トロード	1000
ノソンガルブルス	700
エガイン	のはは本は下のない
1 	i di
エーニ エルハつ	
	> = C
! ハ <u>ハ</u>	ņ
<u>ج</u>	25
NOTIFICATION TAN	37.67.1
<u>.</u>	•

, 6			ΕV	λααΣ-000 P		
9128 H	i	8		, 7		PT
V: 14	. 205		- 		TAP BLK CL	
5:15	On .	(X		SLOW TAF #1		
51.15	3	i.j.,	SPELT TRANS			
5:30	₹ つ	111	IETAL TRAN			
5435	\circ	2.			TAL TR	
5:40	\bigcirc	2			A T III & III II	
5145	N	7				OELAY
6:10	\bigcirc	\mathbf{z}			CHARGE	
6.45	r)	α		CHAMGE		
7:10	i A.)	1.1	SLAG CFF			
7:15	\odot	≥_			SLAC TRANS	
7:18	2	111	REF CL SAMP			
7:40	○	130		THE SHIP SERVICE		
ຊະ ປິເ	•	r		化自己银金 法无权		
8:3C	\circ	2_			SEAC TRANS	
8:30	Û.	2		n G		
8:40	♪	≥				
34:	?	K H	ر بر ا	 		2
FOR DET	! ⊢	ļ	1 1 7 4	FCE 2	1 L	u.

1 1

SEPTENBER 25, 1585

1:42:55 PM FRIDAY

S C MAR		
\ \times \ \ \times \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		0 1 1 0 1
	1 6 6 6 6 8 8 8 8 8 8	• • • • • • • • • • • • • • • • • • •
1		
	<u>г</u> Х	
	:	
		LAG TRAN
		- 4 .
	CH AR GE	
		CHARGE
	3 30 30 6	
	\	SAME SHOW
	`	:
		C) 12 20 20 20 20 20 20 20 20 20 20 20 20 20
		SLAC TRANS
エンテの		
AMFLE SLA		
F () () () () () () () () () (1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	PF3 - FCE
	2 1 1 2 2 2 2 2 2 2	SUMMARY 2 TAP BL TAP BL CHARGE CHARGE MFLE SLAG PF1 -


CHEMETCO
HARTFORD, ILL

ROUTE 3

OLDENBERG RD.

O O O O O

N



OLDENBERG RD.

Koure 3

CHEMETCO HARTFORD, ILL

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION V

DATE:

SEP 2 0 1989

SUBJECT:

Chemetco Plant, Hartford, Illinois

FROM:

John T. Gaitskill, Environmental Engineer

File

TO:

Thru: George Czerniak

This report describes my visit of June 20, 1989, to the secondary copper smelter operations at the subject facility. My host at the plant was Michelle Reznack, Environmental Manager. The visit was for familiarization with the operations in light of reports of high opacities from the plant.

Process Description

This is a one-of-a-kind process in the United States. Copper bearing scrap is refined to 99% pure copper which is cast in 700 pound slabs and sold as anodes to electrolytic copper plants. The exact process is considered to be a trade secret, and a more complete description can be found in confidential documents submitted by the company.

Copper bearing scrap such as radiators, brass piping, and wire are delivered by truck, rail and barge. Once on the premises the scrap is transferred with front end loaders and cranes for processing. Chemetco uses 4 rotating furnaces for copper production. Heat for these furnaces is from natural gas firing. Smelting involves heat with chemical treatment of the scrap to produce molten copper with non-copper material forming a slag layer. The copper is 85-93% pure. Refining then occurs making 99% pure copper by oxidizing out zinc and other impurities. The molten copper is poured for casting into slabs weighing 700 pounds approximately 6 inches thick, 2 feet by 3 feet.

Pollution Concerns

Particulate is the criteria pollutant of concern from this operation. These emissions are generated from several sources. Fugitive dust occurs from material handling traffic. In addition, particulate matter is generated from the furnaces by the burning of insulation on wire and oils and other coatings on scrap. The smelting process generates particulate matter by utilizing large volumes of air to oxidize zinc, and other undesirables in the scrap.

Each of the furnaces is controlled by direct aspiration to its respective wet scrubber for particulate removal. Two of the furnaces also are controlled by common baghouse.

During my visit no tapping or charging could be observed. Furnace #3 was being repaired and required exclusive use of the crane which is needed for moving furnaces during tapping and charging. The smelting and refining processes can be put on hold indefinitely without impairing the product.

Follow-up inspections by CDO to observe these activities will be scheduled.

cc: Penson

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY **REGION V**

DATE

Michigas Camp d'argioni, illinois

FROM John T. Gaitskill, Environmental Engineer

Telefo

Thru: George Czerniak

This report describes my visit of June 20, 1989, to the secondary copper smelter operations at the subject facility. My host at the plant was Michelle Reznack, Environmental Manager. The visit was for familiarization with the operations in light of reports of high opacities from the plant.

Process Description

This is a one-of-a-kind process in the United States. Copper bearing scrap is refined to 99% pure copper which is cast in 700 pound slabs and sold as anodes to electrolytic copper plants. The exact process is considered to be a trade secret, and a more complete description can be found in confidential documents submitted by the company.

Copper bearing scrap such as radiators, brass piping, and wire are delivered by truck, rail and barge. Once on the premises the scrap is transferred with front end loaders and cranes for processing. Chemetco uses 4 rotating furnaces for copper production. Heat for these furnaces is from natural gas firing. Smelting involves heat with chemical treatment of the scrap to produce molten copper with non-copper material forming a slag layer. The copper is 85-93% pure. Refining then occurs making 99% pure copper by oxidizing out zinc and The molten copper is poured for casting into other impurities. slabs weighing 700 pounds approximately 6 inches thick, 2 feet by 3 feet.

Pollution Concerns

Particulate is the criteria pollutant of concern from this operation. These emissions are generated from several sources. Fugitive dust occurs from material handling traffic. In addition, particulate matter is generated from the furnaces by the burning of insulation on wire and oils and other coatings on scrap. The smelting process generates particulate matter by utilizing large volumes of air to oxidize zinc, and other undesirables in the scrap.

Pack of the furnaces is controlled by direct aspiration to its

the furnaces is controlled by direct aspiration to its

the furnaces

electrolled by common baghouse.

During my visit no tapping or charging could be observed. Furnace #3 was being repaired and required exclusive use of the crane which is needed for moving furnaces during tapping and charging. The smelting and refining processes can be put on hold indefinitely without impairing the product.

Follow-up inspections by CDO to observe these activities will be scheduled.

cc: Penson

ROUTING AND CONCURRENCE FORM

Document Subject _ hemetro Plant

Reviewer	Initials	Date
Typist Name Thomore' Originator(s) Name(s) Gardshell	: ICM	9.19.89 19. Sept.8
Reviewers		
Unit Chief		
Section Secretary Section Chief	JC	9/19/89
Branch Secretary		
Division Secretary		
Division Director		•
	9	



ILLINOIS ENVIRONM' L PROTECTION AGENCY Division of Air Pollution Control--Field Operations Section

MEMORANDUM

.4			
	~		

January 14, 1988

Date of Inspection: August 19, 1987

TO:

Miles Zamco

I.D. #: ≤119 801 AAC

FROM:

Jeff Benbenek

Region/District: - 302

SUBJECT:

Facility: Chemetco

SIC 3341

Address:

Route 3 & Oldenberg Road, Hartford, IL 62048

Contact/Title: Gary Roberts/Supt. of Operations Phone:

Phone: 618/254-4381

Facility Description

This facility is primarily engaged in the secondary smelting and refining of copper from copper-bearing scrap metal, drosses, and residues.

The primary product is a 99+ copper casting, referred to as an anode. The raw materials referred to above are smelted and refined in a "four-step process", with these steps being smelting, refining, slag treatment, and slag recovery. Four rotary reverberatory furnaces, (nos. 1-4) known as "Kaldo" converters, are used to accomplish these steps. These natural gas-fired (rated @ 18.9 x 10⁶ Btu/hr.), 70 ton furnaces are interchangeable in that they are identical and can perform each step of this process. According to previous permit applications submitted by this facility, the maximum rate of copper production is 165 tons/day for a 24-hour operating day. According to previous permit applications, the typical process weight rate and operating hours for each step, to produce this amount of copper, can be summarized as follows:

10	~ .	医玻璃管探测器 化二氯甲基	1、 医内侧性畸形 化二甲二甲二甲二甲二甲二甲二甲二甲二甲二甲二甲二甲二甲二甲二甲二甲二甲二甲二甲			C. C	127	COLOR PRODUCTION		11.000110000000000000000000000000000000
·	Step	化玻璃混合物 医静脉 医乳头牙皮炎	10、11年2年後の報告会員	D W	0 111	s/hr.)	1-29-49-46-68		Hours/	n - 1
100	Juch	- 43,000 CA	1000		r. li	/5/ III • /		A COUNTY OF THE PARTY OF THE PA	OUUTS/	IJd V ∂
		 (1) 美容等基準等額以下等等 	化原性线 经通过股票额收益			-, ,	VC3/2550458		CS. 7	
70.7	State of the second	的现在分词 化多合物 计图 化二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十	T. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.	化精色色素化 化二氯甲二甲基	and the second section	and the state of t			A CONTRACTOR OF THE PROPERTY OF THE	and the first of the first
100		POR MENTAL PARTIES.			2. 14 4. C. M. SEE E. M. SEE	10 de			the South Committee of	
100										
9.75	~ -		T. 134 V. 305 H. 1					E1015510000000		Sec. 100
V 9.	Smelt	המוי	garage and the second		· 16 72	76		2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		22.2
44	7111C 1	VIII Y	The state of the state of		15,72	.0				- 5.45
hun		and the second second	ALCOHOLOGICAL STREET	The second section of the second second	Nature 1	arcticl addition	Colorador e Colorador		世の記述を記録を表示して	AF \$400 (88)
	Refir	าว์ทศ			27.73)n	Tarita Salaharan		A Park State of the state of th	70.2
etri.	ne i ii	11110			71.13	11 (A) 25/14/2001			- 14	70.00
			化二二十二十二烷二十二烷	. 胡克斯里拉人物的 感光照视	y. v	一 一次,学习其效果是否	64 .Dir (18 2 Sept 40 Sept		A PERSONAL PROPERTY.	1000
9.7	~ 1	Treatmen		1.0		- C.	在1000年中的大学中的			
100	STAG	irearmer	זד	1 17 4	15,46	· U	學學或是影響的學科。		1.6	513.3
	~	TI Ca pinci		. 1211 (211)	- 4V 5 TV				Service IV	-34.3
14.		_					Charles and the course		SERVICE STREET	- CASA 9006 N. C
- 6.1	Clan.	Recovery	,		11,00	1 0 (1) (1) (1) (1) (1) (1)				100000000000000000000000000000000000000
	Jiau	NECUVE	/		LLLLUL				24	200
alle i	A short reserve a	orace a willing the				T	Asset Carlotte Control of the	SELVER STATE OF THE SECOND	General and Albert J.	a second Sell for

The refining step produces the copper which is then transferred for final fire refining in a 200 ton, natural gas fired anode furnace. The rated heat input to this furnace is 49.6 x 10^6 Btu/hr. The copper anodes are cast from this furnace.

In the slag treatment step, based on the type of raw materials being smelted, a mixture of copper, lead, and tin mixture accumulates. This mixture is transferred to a shaker ladle for separation of the lead-tin alloy from the copper and other materials. The lead-tin alloy is cast into buttons, which is the product. The copper containing mixture is transferred back to the smelting step. This source is not fired by any type of fuel.

Based on AP-42, Section 7.9, particulates are the criteria pollutant of concern in secondary copper smelting and refining. Each of the four converters are equipped with an A.A.F. scrubber system for control of particulates generated during the process mode. These systems are identical and each consist of a quencher, venturi scrubber, and mist eliminator. The maximum pressure drop across the venturi scrubber is 50" H₂O. The primary hood on each system for capturing these process emissions is referred to as a

"snorkel" hood. It is designed to fit over the mouth of the converter for direct evacuation.

For control during charging, each furnace is equipped with low canopy hoods. On converters #1 and #3, the charging hoods are evacuated to two cyclones for primary control and then to two ITK baghouses for secondary control. The charging hoods on #2 and #4 are evacuated to their respective scrubber systems. Booster fans are used to increase draft on the #2 and #4 systems.

For control during tapping, converters #1 and #3, again, use the cyclones and baghouses. Low canopy hoods are utilized. On each of the other two converters, a tapping enclosure is used with a slotted hood at the center which is also evacuated to the scrubber system. Again booster fans are used in these two systems. Particulate emissions from the shaker ladle are also controlled by the cyclone-baghouse systems. Capture is accomplished with the use of a low canopy hood.

The final slag from the smelting and refining process is quenched with water in order to fracture it and it is then screened prior to shipment by rail from the facility. The screen is of the single-deck type and, since water is used in the fracturing process, there is no further control on this source. Fines from the screen are used to line the slag pots.

Steam is provided at the facility by two identical York-Shipley boilers. Fired on natural gas, the rated heat input for each of these boilers is 25.7 x 10^6 Btu/hr. There is no fuel oil standby system on these sources.

It should also be noted that there is no fuel oil capability on the converters or the anode furnace.

<u>Findings</u>

The total time of this plant visit was from 1010 hours to 1440 hours.

After I arrived at the facility, I met with Mr. Roberts and the manager of operations, Mr. David Hoff.

I reviewed the emission inventory with them and requested that they provide me with data on the current production rate of the facility. Mr. Hoff indicated that he would get that information and get back in touch with me concerning it. With regard to changes in sources or control equipment, they informed me that the cyclones and baghouses, for which they received a construction permit (#86040033) on September 2, 1986, have been constructed and are currently in use on converters #1 and #3.

After this discussion, Mr. Roberts and I toured the facility. I noted that the unpaved roadways were being sprayed and a sweeper was being used on the paved traffic areas. Water guns were being used to spray the raw material storage area.

The spare charging hood was on site and it was in good condition. The facility had agreed to keep a spare hood available in response to a Compliance Inquiry Letter in 1986. Mr. Roberts indicated that that hood would be replacing the one on the #2 converter the next day.

We next went to the slag screening area. All final slag produced from the smelting and refining process is transferred to this area where it is first fractured with water and then screened. The fracturing tank and water storage tank have both been fashioned out of a river-going barge. The fractured slag is transferred to a single deck screen for separation. The oversize is sold and the fines are used to line slag pots. I noted that there were water nozzles stationed over the screen, however, Mr. Roberts indicated that they did not work. The construction and operation of the screen indicates apparent violations of 35 Ill. Adm. Codes 201.142 and 201.143 of the Regulations, since no construction or operating permit applications were submitted for this source. It should be noted that it was not in operation at the time of the plant visit.

We proceeded to the location of the cyclones and baghouses. I asked Mr.\
Roberts when this equipment began operation and he responded that he did not know exactly, but it was either in late March or early April of 1987. All units were in operation. There are magnehelics on each of the two baghouses. The East had a pressure drop of 5" H₂O, while the West side was at 3" H₂O. No visible emissions were observed from the exhaust stacks, however, it was not known at the time of that observation if any charging or tapping was taking place in the foundry. There were no visible emissions from the foundry building roof monitor. The ductwork and external structure of these pieces of control equipment were in very good condition. Collected dust is screw conveyed to drums in an enclosed fashion. There was no evidence of any spillage.

At the time of the visit, converters #1 and #2 were in operation. Their respective scrubber control systems were operating as well. The #1 venturi was showing a pressure drop of 44" H₂O. Two pumps were supplying scrubbant to the system with gauges showing 50 lbs. of pressure on the outlets of each. There were no leaks in the piping leading to the venturi. Ductwork was in good condition. There were very light white visible emissions from its exhaust stack. On the #2 control system, the pressure drop was 42" H₂O across the venturi. Again, two scrubbant pumps were being operated with outlet pressures of 58 lbs. and 70 lbs. No leaks were noted from the piping to its venturi. Very light emissions were presented from its stack also. Ductwork was in good condition on this system as well. Mr. Roberts indicated that the venturi nozzles are manually cleaned each shift.

Inside the foundry, I was informed that the #1 converter was in the slag treatment mode, while #2 was refining. 59 tons of material was being processed in the #1 and 80.5 tons was in the #2. I took the following information from monitors in the pulpit:

41	_				aa .	3.32		1.5	N. Sum	- 42 · ·	有效逐		de la company	100				Garage,	9.00			24	26-97-25	134 30		3.5	- N. K.	30.0	200	100
ŗ	ŀι	ırı	ıac	e 1	#	35-37	BI	owe	r F	₹PM	11.5	Mo	tor	An	าตร		Na	tur	โลา	Gá	28	Fl	าพิ		ិ្ឋ	vo	en	F	l nu	,
:	_				/	100									<u> </u>	1.5			 -							ν.,				
à.,						1/4		5,4 4.					IA.	C.	1 17 3		<u>Na</u>		l c	fm) 🦠	60.1136				30 P	cfi	ומ	35.7	23
Ź.	(1994) (1994)		1777			e Sile	1.3		17.69	*		3	· ·		- 30			100	7.		_ ⊹ੌ	27.		, P.,		- 1	<u> </u>	44/		
1	eria.									1837 - 21		ii a	1 P. W.	y	20.5	8.00		3 180	8.50	Anny patricy Vitalian (Maria)			480 V.S	- 4	AAA T	500	Section 1	30 B		6
4	Vii.					A				13. 27	3. 3							7.									and the state of t		2-3	
á	30		:	e 1 - 2 - 1		9.50	1000	14	b/.	247	3/2015	1		Я		и	45.6	2 Feb. 1		n		\$ 130	S		4.		ÆΛ	5.0		rat l
Ž,				4		a V	- 11-4			40.00	- MALESTA		200	- 38		W 15	and a	* 300		· 3				100		Š	U	40.0	A 2000	
4	and the same	- 2	<i>.</i>			7.5	8	13	69				4	Я	14 M. 15				21	? ે		,		Y - 70.	V	- 4	64			2
9			1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -		3.77		7. 794	⊹.= *			50.00		arm a	- 25	3511	100	A. 655 N. G	26546		•		200	500			02	· • •	0.00	of State	λ_{ij}

The #3 converter was idle at the time, but was to be charged for smelting later in the day. #4 was down for rebricking. Mr. Roberts indicated that the converters can be operated for eight months between rebrickings. The shaker ladle was not in operation either and Mr. Roberts informed me that it is normally utilized 1-1/2 hours each shift.

I verified by observation that the #1 and #3 converters' charging and tapping hoods are connected to the cyclones-baghouses. The location of the low canopy hoods for tapping require that these furnaces be tilted toward the charge side of the furnaces for tapping. The #2 and #4 converters tilt in the opposite direction for tapping since that is the location of their enclosures. Ductwork to the primary charging, and tapping hoods was all in good condition. There was minimal leakage of particulates from the primary hoods on #1 and #2. I noted that the charging hood on the #2 converter was in poor condition, especially the top lip. Mr. Roberts reiterated that it would be replaced the next day. According to him, the hood was struck over the weekend by the charging bucket. No charging or tapping took place while I was at the plant, so I could not make any judgment as to the effectiveness of any of the secondary hoods. Anodes were being cast and particulate emissions from the casting wheel were negligible. The same can be said for the anode furnace. Neither of the boilers were operating during the inspection.

After the tour, I reviewed records kept by the facility concerning malfunctions and scrubber parameters.

Records on malfunctions/breakdowns were reviewed from March 1, 1987 to the date of the visit. The day before, while I was driving to another facility in the area, I observed heavy roof monitor emissions from Chemetco. A review of these records showed that they had had a malfunction of the fan on the #3 scrubber system during the same time period. 25,100 pounds of tin cans were charged to that #3 converter during that period. I discussed reporting requirements with Mr. Hoff, Mr. Roberts, and the superintendent of maintenance, Syd Campbell. If the PCB order, 83-2, is still valid, then the facility is required to follow their previously granted operating permit #72090064. The special condition of this permit required that the Agency be immediately notified upon a malfunction/breakdown and that a report be submitted to FOS within five days. There have been delays in getting the written reports and in one instance, no telephone notification or written report was received (May 13, 1987).

I reviewed the records kept of control equipment parameters. Once per shift, the blower motor amperage, pressure drop across the venturi, and scrubbant pump pressure are recorded for each scrubber system. I went back to July 1, 1987 on these records. There was no great deviation in the numbers as recorded. The motor amperage was remained around 40 A.C. amperes. Venturi scrubber pressure drop was in the range of 40-50" H₂O and the pump outlet pressure ranged from 50-60 lbs.

I then informed Mr. Hoff that the Agency's Enforcement Services Section was reviewing the aforementioned Board Order to determine its bearing on permit requirements for the #1-#4 converters and their control systems. If it was determined that that Order did not exempt them from 35 Ill. Adm. Codes 201.143 and 201.144, then it would be included with the Compliance Inquiry Letter being sent due to the lack of permits for the slag screening process.

With regards to particulate emissions, compliance status could not be determined, based on this visit, due to the lack of converter charging or tapping. Follow-up observations would and will be conducted.

With the possibility that the cyclones-baghouses will be connected to the secondary hoods on the #2 and #4 converters, there is no need to update the T.A.S. until that occurs.

JJB:pbo/0061A

cc: DAPC Collinsville

A ROVED: Chief
Engineering Investigation
Section
Date approved

I. Source Identification

A. Name: CHEMETCO

- B. Address: OLDENBERG ROAD AND ROUTE 3
 HARTFORD, ILLINOIS 62408
- C. Air Quality Control Region: REGION 70 METROPOLITAN ST. LOUIS INTERSTATE
- D. Attainment or Non-attainment Area: NON ATTAINMENT (MADISON COUNTY)
- E. Pollutants: SO2, PARTICULATES
- F. Type of Operation: PRIMARY COPPER SMELTER, DOUBLE CONTACT SULFURIC ACID PLANT
- G. Point Source in Violation:
- II. Total Emissions (each pollutant in tons/year)

 SO2

 TSP
- III. Federal Contacts with Source: (dates and main points of discussion)

IV. Status of Local and State Enforcement Actions:

۷. Notice of Violation to be sent to:

Source: (Headquarters and Plant)

CHEMETED

OLDENBERS ROUTE AND ROUTE 3 PLANT:

HARTFORD, EVINOIS 62048

DENIS FERON, PRESIDENT HEADQUARTERS:

CHEMETCO

P.O. BOX 187 ALTON, ELLINOIS 62002

State:

Gary Melvin, Manager Div. of Air Pollution Control

ILLINOIS ENVIRONMENTAL PROTECTION MENCY

2200 CHURCHILL ROAD SPRINGFIELD, IL 62706

Local:

PART II

DATA TO SUPPORT VIOLATIONS AND DESIRED ABATEMENT ACTION (Fill out separate Part II for each point source)

- I. Specific point source in violation:
- Regulation(s) or compliance schedule violated by point source
 (be specific

 FAILURE TO PROPOSE EMISSION OFFSETS 40 CFR PART 51.18

 41 FRESSELY PART IN Condition
- III. Evidence supporting violation:
 - A. Emission Factors

Calculated Present Emissions

Allowed Emissions

Names of individuals who can testify to the above information: G. SILVA

B. Smokereadings for this point source:

Source

Date

No.

No. in Violation

Names of individuals who can testify to the above information:

С.	Stack sampling of this point source: I. Description of stack sampling evidence:
	2. Names of individuals who can testify to the above information:
D.	Evidence indicating missed increment, if applicable:
IV.	Identify and explain any factors which may affect the persuasive impact of the evidence:

۷.

VI. Abatement action(s) which could be taken and a tentative schedule to achieve compliance:

Increments

Proposed types of control

- Submit final compliance plans.
- 2. Award contract for the control device.
- Initiate on-site construction and installation of control device.
- 4. Complete on-site construction and installation of control device.
- 5. Achieve final compliance.
- 6. Submit test data.

VII. If the source has proposed an alternative course of action to the one described above, describe and evaluate the proposed alternative, (attach copy of proposal if available):

acility CHEMETED	Date	and the same and a company of the co	
uculium OLDENBERG ROAD O ROUTE 3	VIEngineer S	/4	
HARTFORD, IL 62408 (MADISON COUNT	y)Ling fried	The second secon	
OUNCE PRIMARY COPPER SMELTER	Sheet of	00	
ollutant SO2	Regulation NS	<i>P</i> 3	
. Production Rate		4	
(Show 1b/hr, ton/yr, and reference) from &	114 info	e ** **	
FEED PRODUCT 8000 16/hr blacky Cu	U	1 3.K	(9)
25,400 10/m Slag 16/nr 9885	A 68 8		
H2804 - 220 tons/day - 18 393	16/hr	± ,,	
	9 -		ž)
II. Emission Factor (Show reference or show calculation)	*		
Pr St			
· · · · · · · · · · · · · · · · · · ·	* 2	# 8. %	
			10 ¹⁰ g
III. Actual Emission Rate (Calculate worst case. Also indicate any Show in units of regulation, e.g. 1b/10 As PER GII4 information Submitted	btu, as well as	s tottil a contyrt	a.
302 - 384 tons/year - 92.6 16/hr @ 1	80° and 14383 C1	FM	
Dai 6 16/hr 673 1hr.	**************************************		
92.6 15/mole × 386.7 673 × 1 hr 64 16/mole × 386.7 mole × 60 min ×10=78	22.9 pom = 0.07	2 6/0	7
14,383 (460+70) SCFM			
460+1801			
		2 n ng 8	

IV. Allowed Emission Rate (Calculate worst case. Also indicate any stack test results or company data. Show in units of regulation, e.g. 1b/10 btu, as well as 1b/hr & ton/yr)

ROASTER - SO2 - 0.065%

uncertain most awant performance lest

acility CHEMETCO	Date	
ocation oldenberg AND Rout 3 HARTFORD, IL 62408	Engineer SI=VA	
State <u>ILLINOIS</u> Source PRIMARY COPPER SMELTER (ORYER) SOLUTION OF PARTICULATE	Sheet of Regulation <u>NSPS</u>	
Production Rate (Show 1b/hr, ton/yr, and reference) § 114 in	ufo	
75,920 16/hr 8000 16/hr - Black Cu		

220 fors/day-18,333 16/hr - 42804

Emission Factor (Show reference or show calculation)

III. Actual Emission Rate (Calculate worst case. Also indicate any stack test results or company data. Show in units of regulation, e.g. 1b/10⁶ btu, as well as 1b/hr & ton/yr)

IV. Allowed Emission Rate
(Calculate worst case. Also indicate any stack test results or company data.
Show in units of regulation, e.g. 1b/10 btu, as well as 1b/hr & ton/yr)

DRYER _ PARTICULATE _ 0.022 gr /dsef